LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

on this certificate.

Schoolcraft (County)	Located In:	Corner Code #	
1. Public Land Survey	T 46N R 16W	E4 G7	
2. Property Controlling in Section	S T R S T R		
3. Miscellaneous Property in Sec.	S T R S T R S T R		
4. Lot No. , Re- 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number 1 A B C D E F G H I J K L N 2 6 5 4 3 2 1
above were in conformance with instructions of the United States	74, Michigan P.A. of 1970, the corne regulations and rules therefore as requipepartment of the Interior, Bureau of corner points mentioned in lines 3, 4 a	ired in the current manual of surve Land Management or by a decree of	2 4 7 8 9 10 11 12 12 5 6 6 18 17 16 15 14 13
the rules of the Michigan Boar re-established, monumented, recov	d of Land Surveyors or by a Decre	e of a Court of Law; established	th 7 d, 8 19 20 21 22 23 24 9 10 30 29 28 27 25 25

A. Description of original monument and accessories and/or subsequent restoration:

(E4) Quarter corner common to Sections 8 and 9. 1954 - Remonumented by Dean C. DeLaMater RLS from one original B.T., found in good condition. Set 1" pipe with 4" brass cap. 10" Beech S87°W 26 links, 6" Soft Maple N69°E 68 links.

(G7) Corner common to Sections 15-16-21-22. 1954 - Dean C. DeLaMater RLS reestablished the corner position by double proportionate measurement to the original record. Set 1"ID I pipe with 4" brass cap. 8" J.Pine S49°E 67 links, 20" R.Pine N45°W 28 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E4) Found the 1954 monument in good condition and at record bearing and distance from the remaining NBT Beech S87°W 26 links, now infected with Beech scale. The Soft Maple NBT N69°E is gone. Any remaining evidence of the original BTs is obscured by deep snow at this time. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(G7) Found the 1954 monument in good condition and at record bearing and distance from the 1954 accessories. The J.Pine SE is down, the R.Pine NW is in good condition with overgrown blazes. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E4) Found 1"ID I.pipe with 4" brass MI Dept. of	
Conservation cap. Set measuring nail with MDNR tag	(G7) Found 1"ID I.pipe with 4" brass MI Dept. of
in the side of:	Conservation cap. Set measuring nail with MDNR
16" Maple N86°E 54.2' mrkd "1/4S NBT"	tag in the side of:
7" Sugar S07°W 6.8' do	22" R.Pine N40°W 19.35' mrkd "S16" 1954 NBT
9" Sugar N71°W 5.1' do	16" W.Pine N06°E 35.65' mrkd "S15 NBT"
6" Maple N27°W 11.0' do	17" W.Pine S45°E 29.8' "S22 NBT"
Center of C.R. 454 East 24 feet.	11" W.Pine S01°W 41.1' "S21 NBT"
E= 8051953.086 N= 179586.473	E= 8053585.206 N= 177181.014

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum Coord. Ref.=NGS PID RK0046: N= 173923.068 m. E= 8052746.340 m. Signed by Date 10/10/2013 Surveyor's Michigan License No. /

33986

For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN J. ZYSZKOSKI LAND SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOA