LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

_						
-0	P	00	t progra	0	me.	in

			l .	
Schoolcraft	_ Located In:	Corner Code #		
(County)	-			
1. Public Land Survey	TR			
2. Property Controlling in Section	S 16 T 47N R 14W S 16 T 47N R 14W S T R	F6 9		
3. Miscellaneous Property in Sec.	S T R S T R		Post to a CP	.
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deed	ds Stamp & File Number
above were in conformance with	n a field survey on 174, Michigan P.A. of 1970, the corner regulations and rules therefore as required Department of the Interior, Bureau of	ired in the current manual of surve	_v 5	9 10 11 12
a Court of Law and /or that the o	corner points mentioned in lines 3, 4 ard of Land Surveyors or by a Decree	nd 5 above were in conformance wit	n 7	21 22 23 24
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town and rang	e, may be recorded	10 30 29 11 12 31 32	-26 - 25 - 25 - 35 - 36 - 35 - 36 - 36 - 35 - 36 - 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (F6) Center of Section 16. 1989 Established by G.L.Wiggins RLS at the intersection of 1/4 lines. Set 1"IDx36" iron pipe with 4" alum. MDNR cap. 20" W.Pine S55W 12.5', 6" W.Pine S26E 6.8', 8" W.Pine NO3W 12.0', 20" W.Birch S8W 2.0'.
- (9) East 1/16 corner, Section 16. 1989 Established by G.L.Wiggins RLS midway and on a straight line between F6 and G6. Set 1"IDx36" iron pipe with 4" alum. MDNR cap. 10" S.Maple S24W 17.4', 12" R.Maple N50W 30.1', 8" R.Maple N12W 32.6', 24" R.Maple N19E 7.0'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F6) Found the 1989 monument in good condition and at record bearing and distance from the 1989 accessories with the exception of the 20" W.Birch S8W 2.0', which was found to bear S80W from the corner. The monument was found 2.58' westerly of the position intended in 1989 and I attribute the difference to a slight error made in 1989. As the monument has not yet been relied upon by local landowners, I removed the 1989 monument and reset it at the intersection of straight lines connecting opposite 1/4 corners, being the position intended in 1989.
- (9) Found the 1989 monument in good condition and at record bearing and distance from the 1989 accessories. The monument was found 4.09' southwesterly of the position intended in 1989 and I attribute the difference to an error made in 1989. As the monument has not yet been relied upon by local landowners, I removed the 1989 monument and reset it at the intended position -- midway and on a straight line between Center of Section 1323.86' west and Quarter corner 1323.86' east.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F6) Set 1"IDx36" I.pipe with 4" alum. MDNR cap set measuring nail with MDNR tag in the side of 20" W.Birch S85W 5.1' mrkd "CS BT" do 3" W.Pine S61W 15.75' do 3" W.Pine N06W 6.7' do 40 do 5" Maple N33W 13.7' do 5" 8071930.400 N= 187784.457	(9) Set 1"IDx36" I.pipe w Set measuring nail with M 24" Maple N18W 4.55' 7" Sugar N59E 14.4' 13" Sugar S31W 21.5' 18" Maple N55W 31.9' E= 8072333.845 N= 187788	IDNR tag in the side of: mrkd "E1/16 BT" do do do

Bearings are magnetic.	Coordinates	are MCS83	in meters.		
Signed by Stephen Smarkers	<u>/</u>	Date	02/13/2013		
Surveyor's Michigan License No.	33986				
Surveyor's Michigan License No./ 33986 For the Michigan Department of Natural Resources, Forest Resources Division					

STEPHAN J SZYSZKOSKI LAND **JRVEYOR** FORM APPROVED BY MICHIGAN STATE BOAT ay 14, 1975 AND SUR Section of the last Revised Oct., 1995