

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
Schoolcraft Co. Three Corners.

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 47 N. R. 15 E.	E-10, D-9, E-9
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 6/22 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
Corners set by Geo. E. Adair, D.S. in 1851.

E-10 Cor. bet. Secs. 28-29, bearings were:
hemlock 13" S74° 13 lks. and hemlock 22" N60° 22 lks.
D-9 Cor. bet. Secs. 20-29, bearings were:
beech 10" S44° 03 lks. and Y. Birch 16" S62° E 32 lks.
E-9 Sec. Cor. 20-21-28-29, bearings were:
sugar 12" S22° 51 lks. and Maple 15" S17° 10' 34 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
E-10 Found remains of old hemlock B.T.s in poor condition. Found wood post, in place and an old blaze, on a down, pine stub, with signatures "S. Lowney and T. Billings, 6/11/51."
D-9 Found an old squared hemlock tree with several signatures. Found Y. Birch stump remains, but could identify none as the witness.
E-9 Corner re-established by Double Prop. Meas. Found no evidence of original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" Aluminium cap at all corners.

E-10 New Bearings:
16" W. Pine N76° W 17.6' and 15" hemlock S25° E 14.8'
D-9 New Bearings:
15" Soft Maple S24° 36.7' and 10" Soft Maple S25° W 7.7'
E-9 New Bearings:
9" Soft Maple N50° E 17.8' and 10" Soft Maple S46° W 26.3'

SIGNED BY Billy D. Buckler DATE 6/27/73

SURVEYOR'S MICHIGAN REGISTRATION NO. 6882 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____