

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 47N R 16W	A8
	T R	(GCDB 100340)
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 08/06/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A8) Quarter corner common to Section 19 T47N-R16W and Section 24 T47N-R17W. 1958 - Remonumented by Billy D. Buckler RLS at the original position as determined from Sugar B.T. S44°W 50 links and stump hole for Sugar B.T. N44°E 25 links. Set 1" pipe with 4" brass cap. 9" H.Maple S13°E 8 links, 12" H.Maple N77°E 41.5 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A8) Accepted the 1958 position as a careful and faithful perpetuation of the position of the original corner. The 1958 monument was not recovered. Remonumented the 1958 position for the corner at record bearing and distance from the 1958 witnesses, both recovered in good condition with overgrown blazes, and described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
17" Sugar S13°E 5.5' mrkd "1/4S" (1958 NBT)
19" Sugar N76°E 28.05' do do
20" Sugar N27°E 20.4' mrkd "1/4S NBT"
12" Sugar N85°W 31.5' do
E= 8048784.752 N= 186039.586



Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum, Epoch 2010.00
Coord. Ref.=NGS PID DJ8902 : N= 177197.949 m. E= 8027768.701 m.

Signed by Stephan J. Szyszkoski Date 03/17/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division