LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	_ Located In:	Corner Code #	
1. Public Land Survey	T 47N R 16W	A9 (GCDB 100300)	
2. Property Controlling in Section	S T R S T R	A7 (GCDB 100400)	
3. Miscellaneous Property in Sec.	S T R S T R		
4. Lot No. , Rec 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number A B C D E F G H I J K L N
above were in conformance with a instructions of the United States I a Court of Law and /or that the c	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require Department of the Interior, Bureau of Lacorner points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree	ed in the current manual of survey and Management or by a decree of 5 above were in conformance with	y 5 of 6 18 17 16 15 14 13 h 7 l, 8 19 20 21 22 23 24
on this certificate.	ers, all in the same town and range,	, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
re-established, monumented, recover NOTE: Not more than 2 corn on this certificate,	d of Land Surveyors or by a Decree ered, found as expressed below:	of a Court of Law; established, , may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

Description of original monument and accessories and/or subsequent restoration:

(A9) Section corner common to Sections 19-30 T47N-R16W and Sections 24-25 T47N-R17W. 1958 -Reestablished by Billy D. Buckler RLS on line between 1/4 cor. 1/2 mile north and 1/4 cor. 1/2 mile south along township line. Set 1/2"x18" iron bar buried in north shoulder of road. 13" Elm N36°E 20 links, 14" H.Maple N69°W 64 links.

(A7) Section corner common to Sections 18-19 T47N-R16W and Sections 13-24 T47N-R17W. 1958 -Reestablished by Billy D. Buckler RLS on the township line between corners 1/2 mile south and 3 miles north. Set 1" pipe with 4" brass cap. 12" H.Maple N61°E 16 links, 15" H.Maple S45°E 54 links, 14" H.Maple S76°W 60 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A9) Found the 1958 monument as described, in good condition 8" below ground level in the north shoulder of an E-W road, at record bearing and distance from the H.Maple NBT N69°W, now dead. The NBT Elm N36°E was not found. Accepted the monument as a careful and faithful reestablishment of the position of the corner.

(A7) The 1958 monument was recovered disturbed by heavy equipment and out of position. Remonumented the 1958 position at record bearing and distance from the stump remains of the remaining two 1958 NBTs. Applying the method used in 1958 to Al and A8 as coordinated this date, the position for the corner was found 5.77' north and 3.48' west of the 1958 position of record and is accepted as a careful and faithful reestablishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A9) Found 1/2" iron bar 8" b.g. in road shoulder. Set measuring nail with MDNR tag in the side of: 8" Y.Birch S28°E 39.55' mrkd "S30 NBT" 11" Sugar S26°W 43.75' "S26 NBT" 10" Sugar N27°W 24.65' "S24 NBT" 9" Sugar N41°E 19.05' "S19 NBT" E= 8048790.736 N= 185234.376	(A7) Reset the 1958 monument, a 1"IDx36" I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of: 12" Sugar N55°W 44.85' mrkd "S13 NBT" 18" Sugar N10°W 37.85' "S13 NBT" 14" Sugar S30°E 29.05' "S19 NBT" 13" Sugar S30°W 49.1' "S24 NBT" E= 8048777.932 N= 186844.431
---	--

Bearings are magnetic. Coord. Ref.=NGS	Coordinates are NS PID DJ8902 : N= 1	MCS83 in meters .77197.949 m. E=	(NAD83 (2011) 18027768.701 m	Datum, F		
	spelist.	Date	03/17/2015	13	STEPHAN J. SZYSZKOSKI	
Surveyor's Michigan License No. /	33986		10		LAND	
For the Michigan Department of Natural Resources, Forest Resources Division					SURVEYOR No.	

FORM APPROVED BY MICHIGAN STATE BOARD

ovised Jan., 1983 Revised Oct., 1995

AND SRANE