LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N., R. 5 W.	I-10,H-9,G-10,H-11
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 6, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

B. Continued: Register of Deeds.

C. Continued:

H-11

Set DNR mon. & ced. post

3" Ironwood	N15°W	14.5
4" Maple	S64°E	8.6
15" Maple	S24°W	17.5

Fd. R.R. spk. by cor. fn.
post(fn. W & N) S73°12'E 51.8'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-10 Reestab. E 1/4 cor. Sec. 27, midway & on line between NE & SE cor's. of Sec. 27.

H-9 Reestab. N 1/4 cor. Sec. 27 midway & on line between NE & NW cor's. of Sec. 27.

G-10 Reestab. 1/4 cor. to Sec's. 27 & 28 midway & on line between fd. NW & SW of Sec. 27. E.A. Robinson searched for Govt. cor. here in Jan. 1908; could not locate so estab. S.P. 1/4 cor. We looked for cor. nothing but wet dead Ash swp. An old fn. cor. B-W, S-E-W is 48'N & 59'W. The fn is not noted in Robinsons notes & does not look that old.

H-11 Reestab. 1/4 cor. to Sec's. 27 & 34 per E.A. Robinson survey Jan. 1908. He searched for 1/4 cor. for 2 hrs "but could not find any"-"Fd. old blaze E & W but it is crooked". (No mention of fn's here but he does note same elsewhere in this twp.). He reestab. ¼ cor. by single proportion bet. fd. SE Sec. 27 & reestab. SW Sec. 27 by double proportion See "Melrose" book, Pgs. 53 thru 59; old Co. Surveyors Records in Jury Room across from

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-10

Set DNR mon. & ced. post.

5" Maple(Cluster)	North	41.5
2" Maple	S65°E	58.6
12 Maple twin	S05°E	151.3
Logging trail SE & SW	South	195'±
N-S random	East	0.9'

H-9

Set DNR mon. & ced. post

7" Cedar	N55°E	23.5
6" Cedar	N15°W	24.0
14" Cedar	S65°E	17.1
E-W random	North	1.8'

G-10

Drove 1" x 6' pipe w/DNR cap & ced. post

7" W. Birch	N45°E	20.4
5" W. Birch	S05°E	20.7
6" Balsam	S85°W	2.9

Ctr. R.R. tracks
N88°15'W 707'±

SIGNED BY Carl F. Roser 01-12-82 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET