LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 45 N. ~~S.~~, R. 34 ~~E.~~ W.	B5, C4, and C5
2. PROPERTY CONTROLLING IN SECTION _____	,T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	,T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19__, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner B5: Wood post Not found. Found a squared cedar S75°E 121 lks.
Fir 8 N65W 65) Not found. No subsequent accessories found.
Fir 10 S40E 50)

Corner C4: Wood post
Sugar 12 N85E 23) Not found. No subsequent monuments found.
Sugar 10 S85W 35)

Corner C5: Wood post Not found. Found wood post S54°W 66 lks.
W. Pine 10 S35W 19) Not found. No subsequent accessories found.
Y. Birch 8 N75E 13)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner B5: Re-established 11/27/72 proportionately on line between section corners 40.086 ch. E and 39.216 ch. W. 12" cedar had been blazed for an approx. corner by unknown parties, probably foresters.

Corner C4: Re-established 11/24/72 on line between section corners 40.055 ch. to N & to S.

Corner C5: Re-established 9/19/72 at record distance E of a corner on west twp. boundary, and proportionately from section corners 1 mile N and 1 mile S. Found this procedure to be more harmonious with record calls to natural objects than is a strict double proportion, because of apparent measurement errors in original government survey. Wood post set by unknown persons for an approx. corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for all three corners: 1" I.D. x 36" iron pipe with 4" aluminum cap.

Witnesses for Corner B5: Red Maple 10 S77°E (mag.) 12.0 ft. "1/4S, NBT"
Red Maple 10 S40°W (mag.) 19.1 ft. "1/4S, NBT"
Red Maple 12 N43°W (mag.) 10.2 ft. "1/4S, NBT"

Witnesses for Corner C4: Sugar Maple 7 N49°E (mag.) 4.6 ft. "1/4S, NBT"
(Variation 0°55' East) Sugar Maple 8 S36°E (mag.) 24.4 ft. "1/4S, NBT"

Witnesses for Corner C5: Red Maple 7 N82½°W (mag.) 28.1 ft. "S7, NBT"
Red Maple 6 N 3½°E (mag.) 7.3 ft. "S8, NBT"
Red Maple 5 S43°E (mag.) 3.7 ft. "S17, NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE December 28, 1973
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

Form No. ML M736
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS