LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Beardcraft Co.   Two Corners.

FOR CORNERS OF-:	LOCATED IN-:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 41 N. S. R. 13 E. W.	E-1, D-1
2. PROPERTY CONTROLL-ING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO._____ , RECORDED PLAT_____

5. PRIVATE CLAIMS_____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, __Billy D. Buckler__ do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram — over) were, in a field survey on ___3/30___ 19 73, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__ , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

   E-1   Sec. Cor. 4-5, T41N R13W and Secs'. 32-33, T42N R13W. set by John Burt, D.S. 1845.
   Bearings were:
   Cedar 8"   N52°E 25 lks. and Cedar 9" N81°W 24 lks.

   D-1   ¼ Cor. on Northside, Sec. 5.
   Bearings were:
   Cedar 10" N60°E 9 lks. and Fir 7" N55°W 9 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

   E-1   Found old wood post in place with two older stake bottoms in ground. No
   evidence of original witnesses. Found a line of very old blazes to West.

   D-1   Re-established corner on line with corner ½ mile East and Twp. corner, 1½ miles
   West and at record distance from Corner to East.
   No evidence of original corner. Distance West to lake is good.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
   Placed 1" pipe with 4" aluminium cap at both corners.

   E-1   New Bearings:
   12" Cedar East 60.6' and 8 " Cedar S8°E 64.4'

   D-1   New Bearings:
   4" Cedar S87°E 44.4'

SIGNED BY____Billy D. Buckler____ DATE ___6/27/73___

SURVEYOR'S MICHIGAN REGISTRATION NO. ___8887___   (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY_____ DATE _____
          CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY_____ DATE _____
          MICHIGAN REGISTERED LAND SURVEYOR   (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____