LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co. Two Corners

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. ____ N. S., R. ____ E. W.	Meander Cor. South C-3 Meander Cor. South E-4 on Lake Mich.
2. PROPERTY CONTROLLING IN SECTION 8	T. 41 N. S., R. 11 E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION ____	T. ____ N. S., R. ____ E. W.	

4. LOT NO. ____, RECORDED PLAT ____

5. PRIVATE CLAIMS ____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 9/25 19 69, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

M.C. South of C-3 Original witnesses were:
W. Pine N70°E 26 Links
W. Pine N47°W 37 Links
Marked by John Burt, D.S. Aug. 1845

M.C. South of E-4 Original witnesses were marked by John Burt, D.S., Aug. 1845.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M.C. South of C-3 Found remains of possible witnesses in proper position, with blazes and what appear to be witness marks but no scribe marks. Position checks well with Sec. Cor. to North and meanders of the lake shore.

M.C. South of E-4 Meander Corner placed on an old blazed line, which bears South from the ¼ Cor. bet. Secs' 8-9. No evidence of original Cor.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminum cap at both corners.

New Bearings:

M.C. South of C-3 12" Y. Pine S22°W 25.2'
10" Y. Pine N23°E 18.1'

M.C. South of E-4 12" Cedar N72°E 9.1'
8" Cedar S42°E 14.4'

SIGNED BY Billy D. Buckler DATE 6/14/1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ CHIEF OF SURVEY PARTY DATE ____

APPROVED AND SIGNED BY ____ MICHIGAN REGISTERED LAND SURVEYOR DATE ____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. ____

Form No. MLM736
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS