SURVEY'S
DOCUMENTATION

LAND CORNER RECORDATION CERTIFICATE LIBER **316** PAGE **308**

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

PRESQUE ISLE
(County)

Located In:

Corner Code *11*

PRESQUE ISLE COUNTY
RECORDED

95 OCT 20 PM 4:32

REGISTER OF DEEDS

1. Public Land Survey   T 36N R 2E   I-2
   T ___ R ___
   T ___ R ___
   T ___ R ___

2. Property Controlling   S ___ T ___ R ___
   in Section   S ___ T ___ R ___

3. Miscellaneous   S ___ T ___ R ___
   Property in Sec.   S ___ T ___ R ___

Register of Deeds Stamp & File Number

4. Lot No. _____ , Recorded Plat _____

5. Private Claims _____ _____

I, Ronald Bischer, in a field survey on ____ July 21 ____, 19 95 ,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

```
GLO Resurvey Notes - 1856          N68°E   13.87'    9" Hemlock
Geo H. Cannon                      S66°E   22.21'    6" Maple
Set wood post                      S08°W   20.88'    8" Cedar
Hemlock 14"  N20°W  11 lks         S34°W   37.85'   20" Cedar
Aspen    10"  S40°E  14½ lks
                                   01-24-95 - Ronald R. Bischer
02-05-93 - Ronald R. Bischer       same as 02-05-93
Set ½" Rod from OBT stump and
  at recorded distance from
  stream in GLO notes.
```

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

```
Found ½" Rod and Cap #22428
N68°E   13.87'    9" Hemlock
S66°E   22.21'    6" Maple
S08°W   20.88'    8" Cedar
S34°W   37.85'   20" Cedar
South   78'      stream
        (1.20 ch.)
```

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

```
½" Rod and Cap #22428
N68°E   13.87'    9" Hemlock
S66°E   22.21'    6" Maple
S08°W   20.88'    8" Cedar
S34°W   37.85'   20" Cedar

Nails with witness tag #22428 used.
```

STATE OF MICHIGAN
RONALD BISCHER LAND SURVEYOR NO. 22428
REGISTERED LAND SURVEYOR

Ratified by **Peer Group**
in accordance with P.A. 345
Chairman _____
Date 9/26/95

Signed by _Ronald R. Bischer_ _____ Date _Oct. 3, 1995_

Surveyor's Michigan License No. _22428_