

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

DICKINSON COUNTY			
FOR CORNERS OF--:	LOCATED IN--:		CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. 43 N. X. R. 29 X.		A5, A6
2. PROPERTY CONTROLLING IN SECTION 18	T. 43 N. X. R. 29 X.		3
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. X. R. _____ E. X.		
4. LOT NO. _____, RECORDED PLAT _____			
5. PRIVATE CLAIMS _____			

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on See Below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- Corner 3: Not set on original survey nor subsequently apparently.
 - Corner A5: Found old Cedar post set from possible original B.T. Cedar 14" N42E 32 lks. B.T. lying down and well rotted with old axe marks.
 - Corner A6: Found two old pine stumps matching for distance and bearing. Old axe marks on stumps but rotted where scribing would have been.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- Corner 3: Established 5-21-81 by proportion between 1/4 corner south and original line tree north.
 - Corner A5: Restored 5-27-81 at old post corner; fits good north and south but distance is short to stream east.
 - Corner A6: Restored 5-21-81 from old pine stumps. Fits good with other corners.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Corner 3: Set 1" I.D.x36" iron pipe with 4" alum. cap.
 - 12" tamarack N33W 24.0 ft. 1/16S,BT
 - 8" Tamarack N78E 31.3 ft. 1/16S,BT
 - 5" Spruce S61W 18.2 ft. 1/16S,BT
 - Corner A5: Set 1" I.D.x32" Iron Pipe with 4" alum. cap.
 - 14" Tamarack S80W 39.2 ft. S13,NBT
 - 8" Spruce N59E 49.2 ft. S7,NBT
 - Corner A6: Set 1" I.D.x32" iron pipe with 4" alum. cap.
 - 4" Spruce N53W 11.2 ft. 1/8S,NBT
 - 6" Spruce S59E 20.1 ft. 1/8S,NBT
 - 7" White Birch N40E 12.0 ft. 1/8S,NBT

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____


(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Keith L. Sackett DATE _____

CHIEF OF SURVEY PARTY
 MICHIGAN REGISTERED LAND SURVEYOR
Keith L. Sackett
 Department of Natural Resources



SURVEYOR'S MICHIGAN REGISTRATION NO. 19006