

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>43</u> N. <u>33</u> E. R. <u>33</u> KK W.	A9 & A10
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. _____ E. S., R. _____ W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. S., R. _____ W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on see below 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A. Corner A9: Sugar post
 Hemlock 8 S32½E 52 Sugar 10 N65E 50
 Sugar 12 N64W 32 Sugar 10 S25W 51
 Original post or accessories not found. Found an old drill rod and wood post cast in concrete 1.453 ch. E, of recent vintage, set by unknown persons, which purports to be this corner. No record found.
Corner A10: Hemlock post (Not found)
 Hemlock 14 S53E 18 {Not found.) No subsequent accessories found.)
 Cedar 14 N70W 40

Found a 1½" I.D. x 27" iron pipe in place as set by unknown persons many years ago, from unknown evidence. No record of establishment found.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner A9: Re-established 11/6/72 proportionately on line between ¼ cor. 40.091 ch. S and Sec. Cor. 80.182 ch. N. Discounted the found drill rod as being too far off line to be consistent with original evidence recovered along this township line.
Corner A10: Monument accepted as found, as it is consistent with other original evidence developed to the north along this township line. Also consistent with swamp edge .50 ch. S as recorded in original field notes.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for both corners: 1" I.D. x 36" iron pipe with 4" aluminum cap.
Witnesses for Corner A9: Sugar Maple 7 N25°W (mag.) 8.3 ft. "S24, NBT"
 (Variation 2°20' West) Sugar Maple 5 N69°E (mag.) 13.6 ft. "S19, NBT"
 Sugar Maple 6 S27°E (mag.) 20.1 ft. "S30, NBT"
 Sugar Maple 6 S15°W (mag.) 12.1 ft. "S25, NBT"
 Also blazed and scribed a 6" sugar maple N68°W 2.8 ft. from corner.
Witnesses for Corner A10: Cedar 6 S34°E (mag.) 97.1 ft. "1/4S, NBT"
 Red Maple 10 N13°E (mag.) 62.1 ft. "1/4S, NBT"
 (Variation 1°00' West) Nail with 3/4" brass ref. marker on NW'ly side of WMPC power pole No. 16507, S54½°W (mag.) 45.1 ft.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE February 27, 1974
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger
 Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

