

**SURVEY &  
REMONUMENTATION**

**AUG 13 1998**

**MACKINAC COUNTY REMONUMENTATION CORNER**

**SECTION**

For corners in

Mackinac  
(County)

Located In:

Corner Code #

1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 36 T 42N R 1W	_____
	S 31 T 42N R 1E	# 1
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

**RECEIVED & FILED**  
DIANE FRANKOVICH  
MACKINAC COUNTY REGISTER OF DEEDS

**AUG 11 1998**  
AM 7|8|9|10|11|12|1|2|3|4|5|6  
PM

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Neil E. Hill, in a field survey on August, 6, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

1840	GLO notes	William Burt	9" Tamarack	N58½W	72 links
			4" Fir	S84W	27 links
1973	Survey by Mary C. Fiendt		Set ¾" pipe and cap	Liber A Pg. 95-96	
1985	Survey by Larry R. Rogers		Found ¾" pipe.		
1998	See reverse side for a full detailed history of the corner.				

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

1997 Remonumentation survey by R.S. Scott Associates, Inc.

Found ¾" pipe.

This corner position is compatible with County and local surveys. This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

1997 Placed a 3" Mackinac County remonumentation Cap Stamped to identify the corner, over a ½" iron rod in a ¾" pipe, in a monument box.

Referenced: N 09 W 137.89 P.P.

(Exist.) N 16 E 76.30 P.P.

(Exist.) S 11 E 109.20 P.P.

S 67 E 38.45 4" Scotch Pine

1998 As requested by the Michigan Remonumentation Commission, the corner is re-recorded by the Mackinac County Surveyor, to correct a designation problem. No resurvey or check of witnesses was performed, only the designation problem was corrected, and full history added to the form.

Signed by Neil E. Hill P.S. Date August 6, 1998

Surveyor's Michigan License No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

**E-223**

