

**SURVEY &
REMONUMENTATION**

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

APR 28 1995

LAND CORNER RECORDATION CERTIFICATE

1994 DEC 29 PM 1:54

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

Patricia A. Moseley
REGISTER OF DEEDS

For corners in
Marquette
(County)

Located In:

Corner Code #

1. Public Land Survey	T	<u>46N</u>	R	<u>25W</u>	<u>I-13</u> ✓
	T	<u>45N</u>	R	<u>25W</u>	<u>I-1</u>
	T		R		
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous Property in Sec.	S		T	R	
	S		T	R	

**RATIFIED BY PEER GROUP
P.A. 345 OF 1990**

Larry J. Bussard
DATE Sept 12, 1994

LIBER **1** PAGE **207**
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Michael Mileski

September 94

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
I-13; Southwest Corner Section 35;

See back of form.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-13; Southwest Corner Section 35;

Found no evidence of either U.S. or M.C.R.C. monumentation or accessories. Reestablished the southwest corner of section 35 at proportionate distance along an arc connecting the southeast corner of section 36 and the south one-quarter corner of section 34.

State Plane Coordinates

Grid System - NAD 83
Zone Number - 2111 Michigan North
Units - International Feet
Y = 565332.83767
X = 26143724.77136

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-13; Southwest Corner Section 35;

Set 3/4" x 24" iron rod with 3" aluminum cap appropriately stamped as to location.

W1: SE Corner Concrete Light Pad	N10°E	105.34'
W2: North Bolt of Light Pole mkd. with "X"	S44°E	117.67'
W3: Top of Hydrant	S02°W	244.40'
W4: NE Corner Concrete Light Pad	N54°W	28.29'

See sketch on back of form.

Surveyed by Michael Mileski

Date 21 Nov 1994

Surveyor's Michigan License No. 39091



	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Ref 6476
900
200 35M

A. Description of original monument and accessories and/or subsequent restoration:

I-13; Southwest Corner Section 35;

Originally established during U.S. Survey conducted by Wm. A. Burt, D.S. for Douglass Houghton, D.S. in 1844 and monumented with a wood post witnessed by a Spruce Pine 9 N24°E 25 lks.
and a
Spruce Pine 10 N72°W 20 lks.

And from the 1852 subdivision notes of T45N, R25W a
Spruce Pine 15 S67°W 26lks.
and a
Spruce Pine 16 S30°E 15 lks.

During the course of a survey conducted by the Marquette County Road Commission in 1941 and described in M.C.R.C. field book 712 all U.S. corners lying between the south one-quarter corner of section 36 and the southwest corner of section 34 were considered lost. The south one-quarter corner of section 36 and the southwest corner of section 34 were both considered by the Marquette County Road Commission as legitimate U.S. corners and all intermediate standard corners except possibly the south one-quarter corner of section 35 were monumented with a 1" iron pipe and jack pine post at the appropriate proportioned position. Refer to M.C.R.C. field book 712 pages 8 & 9.

The M.C.R.C. noted the following new bearing trees as of 15 December 1941:

- 6" Jack Pine S48½°E 34.2'
- 5" Jack Pine S50°W 19.5'