

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Osseo
 (County)

Located In _____ Corner Code # _____

- | | | | | | |
|--------------------------------------|-------------|--------------|-------------|--|----------|
| 1. Public Land Survey | T _____ | R _____ | | | |
| | T _____ | R _____ | | | |
| 2. Property Controlling in Section | S <u>36</u> | T <u>29N</u> | R <u>1W</u> | | <u>9</u> |
| | S <u>36</u> | T <u>29N</u> | R <u>1W</u> | | <u>6</u> |
| 3. Miscellaneous Property in Section | S _____ | T _____ | R _____ | | |
| | S _____ | T _____ | R _____ | | |

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on June 23, 2003 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

9- G. D. Henning 1966 placed 1/2" bar and stake
 Wit: 8" B. Oak N17°E 23.7'
 8" B. Oak S64°E 31.7'

6- G. D. Henning 1966 Set 1/2" bar and post
 Wit: 6" R. Oak S75°W 31.4'
 8" R. Oak S19°E 61.5'

Larry G. Beauregard 1977 found "T" iron set by Henning
 Wit: N17°E 8" B. Oak 23.7'
 S64°E 8" B. Oak 31.4'

Larry G. Beauregard 1977 found "T" iron set by Henning
 Wit: S19°E 61.5' Red Oak 8"
 S45°W 19.88' P. Pole

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

9- During the course of a 1968 survey by Norman C. Caldwell he found that a previous monument set for the Southwest corner of section 36 by The Department Of Conservation had been set in error. Surveys by G.D. Henning in 1966 and Larry G. Beauregard in 1977 used this erroneous corner for section subdivisions. In June of 2003 I re-subdivided section 36 using the adjusted Southwest corner and established the Northwest corner of the Northeast quarter of the Southeast quarter of section 36 as per B.L.M. instruction for the subdivision of a section.

6- During the course of a 1968 survey by Norman C. Caldwell he found that a previous monument set for the Southwest corner of section 36 by The Department Of Conservation had been set in error. Surveys by G.D. Henning in 1966 and Larry G. Beauregard in 1977 used this erroneous corner for section subdivisions. In June of 2003 I re-subdivided section 36 using the adjusted Southwest corner and established the Northwest corner of the Southeast quarter of the Northeast quarter of section 36 as per B.L.M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

9- Set 5/8" X 32" capped iron rod with P.S. cap #33981
 Wit: 6" J. Pine N64°W 2.18'
 1/2" iron N13°W 7.17'
 5" J. Pine S18°W 36.90'
 12" Oak S43°E 45.98'
 Carsonite Post North 1'±

6- Set 5/8" X 32" capped iron with P.S. cap #33981
 Wit: 12" J. Pine S35°E 40.28'
 P. Pole S53°W 16.58'
 11" Oak N58°W 16.58'
 10" R. Pine N67°E 34.64'
 1/2" iron N17°E 4.01'
 Carsonite Post North 1'±

Signed by: _____

Carl T. Kiiskila

Date: 11-18-03

Surveyor's Michigan License No.: 33981

