

MAY 10 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>WEXFORD COUNTY</u>	Located In:	Corner Code #
1. Public Land Survey	T <u>21N</u> R <u>09W</u>	<u>G-6</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECEIVED
 1999 DEC -1 PM 3:06
Richard D. Wilcox
 WEXFORD COUNTY MI
 REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, George D. Smith, P.S., in a field survey on June, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2			1
3												
4	7		8		9		10		11			12
5												
6	18		17		16	●	15		14			13
7												
8	19		20		21		22		23			24
9												
10	30		29		28		27		26			25
11												
12	31		32		33		34		35			36
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- G-6) 1848 GLO subdivision by Orson Lyon D.S. 12" Maple-S41 1/2 E-13, 17" Maple-S65 1/2 W-42.
- 1880 AJ Teed Liber 1, Page 25. Corner found no description or witnesses given.
- 1907 D. Teed Survey, Liber 1, Page 26. Corner found 30" W. Pine-N66 1/2 E-119, 24" W. Pine-S54E-114, 30" W. Pine-N71 1/2 W-78, 20" W. Pine-S32W-81.
- 1907 D. Teed Survey, Liber 1, Page 27. Corner found no witnesses given.
- 1962 MSHD Government monument witness recorded by G. Slattery, Liber 2, Page 890. Boat spike flush with road, set by MSHD Const. N76E-46.58'-15" Elm, S35E-51.98'-Pine Road sign, S86W-68.55'-5" J. Pine.
- 1966 Shadko Survey for Michigan Department of Conservation (not recorded). Found 3/4" pipe, set 4"x42 monument with brass cap. W. Pine 16"-N65E-134.25, R. Pine 12"-N36E-91.90, J. Pine 6"-N65W-63, W. Pine 18"-S23E-175.00.
- 1975 Plat of Harmony Hills by F. Finnerty, PS #16038, Liber 7, Pages 305-311 of plats. Corner found no witnesses given.
- 1976 Plat of Harmony Hills, No. 2 by F. Finnerty, PS #16038, Liber 7, Pages 320-322 of plats. Corner found no description or witnesses given.
- 1990 Carlson, PS #24589, LCRC Liber 4, Page 68. Found 4" brass cap in concrete. Power pole-S47W-44.77', fence corner-S85W-34.56', 26" W. Pine-N82E-74.43', 8" J. Pine-S48E-76.48', Elm stump (old)-N79E-46.3'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- G-6) Found 4" brass cap in concrete in monument box. This corner is accepted as the best available evidence of the position of the original corner being the quarter corner common to Sections 15 and 16, T21N, R9W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-6) 4" Brass cap in monument box
- S78W 112.48 Powerpole
- S55W 72.25 12" R. pine
- S16E 129.54 6" J. pine
- S31E 88.58 6" Twin elm



Peer Group Reviewed and Approved
 Date: 12 Nov 99
Richard D. Wilcox
 Richard D. Wilcox, Wexford County Surveyor

Signed by _____
 Surveyor's Michigan License No. 39098

Date 11-12-99