

SURVEY &
REMONUMENTATION

FEB 19 1998

05-57

Approved by Alger County
Land Survey Commission
Peer Group 1, 1997, 1998 of
P.A. of 1990 On 12-10-97

Gerald W. Jackson
Chairman

SECTION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

_____ (County)

Located in:

Corner Code #

1. Public Land Survey	T	46	R	17	C12
	T		R		
	T		R		
	T		R		
2. Property Controlling	S		T	R	
in Section	S		T	R	
3. Miscellaneous	S		T	R	
Property in Section	S		T	R	

FILED
TIME 8:30 A.M.

DEC 17 1997

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	6	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Robert L. James, in a field survey on November 07, 1997, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C12: PLS - William Ives, SS. 1850 * Set quarter section post * Yellow Birch 16, S.77 E. 12 links * White Pine 30, N.79 W. 26 links
***** George L. Depew, County Surveyor, 1917 * Set standard iron corner according to field notes * No references given ***** M.D.S.H.
Right of Way Maps for Highway M-94, 1959 * Approximate crossing of East-West quarter line shown by station only ***** No other subsequent restoration on record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No corner monument found in Asphalt Highway of M-94 * Found concrete right of way markers of M-94 at approximate East-West quarter line crossing * Established corner position on true line midway between corners North and South * Established corner position relates closely to exist. concrete right of way markers and lies in North bound lane of M-94 * Corner position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Installed a 5/8 inch by 19 inch Rebar w/Berntsen Alum. cap no. RBD 5925, stamped to identify corner position * Corner position lies approximately 4 feet East of centerline pavement on M-94 * Established references with 8T signs, blazed, scribed and painted * Set PK nails w/Alum. I.D. washers in the following - White Pine 8, N.55 W., 66.32 feet, "1/4S BT" * Balsam 14, S.64 W., 82.18 feet, "1/4S BT" * Spruce 6, N.66 E., 66.93 feet, "1/4S BT" * Balsam 6, S.56 E., 83.16 feet, "1/4S BT" * All bearings are magnetic.

Signed by

Robert L. James

Date

12/10/97

Surveyor's Michigan License No.

25849

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

