## SURVEY & MONUMENTATION

Surveyor's Michigan License No.

SURVEY & EMONUMENTATION	Approved by Aught County Land Survey Flamonumentation Peer Group Under Act 845 of
JAN 182001	P.A. of 1990 On 12-13-13-20-20-
For corners in LAND CORNER RECORDATION CERTIF	FICATE Gulacon
SECTION Filing Requirement of Act 74, Mich. P.A	1. 1970 Chairman
Alger Located In: Corner Code #	
	FILED
1. Public Land Survey T 46N R 17W G01	TIME So Am
T 47N B 17W G13 / T R	DEC 2 0 2000
T R	DONALD W. KINNUNEN
2. Property Controlling S T R	REGISTER OF DEEDS
3. Miscellaneous S T R	ALGER COUNTY, MI Register of Deeds Stamp & File Number
· •	register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L
5. Private Claims	2-6-5-4-3-4-1-3
	3
Robert L. Jamros in a field survey on July 19 2000	4 7 4 8 9 10 11 12 12
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points ment	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the creanual of survey instructions of the United States Department of the Interior, Bureau of	Land 7
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or	
Decree of a Court of Law; established, re-established, monumented, as expressed below:	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	11 + + + + + + + + + + + + + + + + + +
on this certificate.	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration	):
N.81°E., 35 links. (Blank) 14", N.28°W., 28 links. * Section corner on North boundary. Beech 14", S.36°E., links. ***** Michigan Department of Conservation, Forestry 1960. Set 1" iron pipe with 4" brass cap by double proper corners to East, West, South and % corner North. Hemlock Maple 10", (S3 NBT) S.22°E., 28 links. Maple 12", (S33 Page 209, Alger County corner records. ***** No other subse	44 links. Beech 8", S.72°W., 29 privision. Billy D. Buckler, RLS, portionate measurement using section 10", (S34 NBT) N.65°E., 44 links. NBT) N.30°W 54 links. Liber 2,
8. Description of corner evidence found and/or method applied in restoring or reest	ablishing corner:
<b>G01:</b> Found 1" iron pipe with 4" brass cap and 2 NBT's of NBT bearing Northeast from corner gone. Measurements between with measurements from this corner West and South. Existical careful and faithful reestablishment of the position of the second	een corners in this area agree well ng monument position is accepted as
C. Description of monument for corner and accessories established to perpetuate I	ocating the position of the corner:
GO1: Existing 1" iron pipe with 4" brass cap as found. R and paint. Established reference trees with BT signs, bl nails for measure with aluminum I.D. washers in the follow 35.37 feet (blaze scars); Ex. NBT, Maple 16", S.19°E., 18 S.72°W., 10.51 feet (S4 BT); Maple 14", N.62°E., 35.47 fe 6 foot steel post, S.45°E., 1.0 feet. All bearings are mage	azed, scribed and painted. Set PK wing: Ex. NBT, Maple 30", N.29°W., .96 feet (blaze scars); Maple 14", et (S34 BT). Survey marker sign on
	137
	ROBERT L.  JAMROS PROTESSIONAL SURVEYOR  No.
Signed by fallul of famile Date	Dec 17, 2000 25349
Surveyor's Michigan License No. 25849	OFESSIONAL