

DEC 27 1999

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 840 of
P.A. of 1990 On 12-8-1999

Donald W. Kinnunen
Chairman

06-151

For corners in
SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

ALGER (County)	Located In:	Corner Code #
1. Public Land Survey	T 50N R 13W	MC E13 F13 ✓
	T 49N R 13W	MC E1 F1
	T R	
	T R	#5
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Section	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

FILED
TIME 1:30 pm

DEC 15 1999

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on May 26, 1999, 19_____,
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
MC5: PLS * John Burt, DS, 1841. * 69.41 chains and intersect Bay and Lake Superior and set meander post. * Y.Pine 18", N.38 E., 82
links. * W.Pine 16", N.48 W., 38 links. * Coast bears S.51 E. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
MC5: Extended township line from the Southeast corner and South 1/4 section corner of Section 33 westerly to the existing shore of
Lake Superior. Position found to be 1371 feet East of GLO meander corner position. Established a witness corner at 110 feet East from
shoreline and 1481 feet East of meander corner position. Witness corner as established is accepted as a careful and faithful
reestablishment of a witness to the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
MC5: Set 2 1/2"x30" Berntsen aluminum monument No. A1NB30 with 3 1/4" aluminum cap as witness corner, stamped to identify corner
position as 1481 feet East of meander corner. * Established the following reference trees with BT signs, blazed and scribed. * Set PK
nails for measure with aluminum I.D. washers in the following: R.Pine 8", S.37 E., 15.31 feet, "BT". * R.Pine 9", S.65 W., 19.84 feet,
"BT". * R.Pine 8", N.62 W., 14.56 feet, "BT". * W.Pine 16", N.43 E., 20.06 feet, "BT". * Survey marker sign on 6 foot steel post, N.22
E., 1.5 feet. * All bearings are magnetic.

Signed by *Robert L. Jamros*
Surveyor's Michigan License No. 25849

Date DEC 15 1999
