

RE

MAR 07 2000

ALLEGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Allegan

(County)

Located In:

Common corner

Corner Code #

1. Public Land Survey

T R

T4N R11W

T4N R12W

A-9 Leighton ✓

M-9 Dorr

2. Property Controlling
in Section

S

T

R

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Robert J Jonker, in a field survey on 12-8, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO survey - East Boundary - M-9
North - E. side 25
80.0 ch. set post se 24 and 25
R. oak 9 N42°W 43'
W. oak 15 S5°W 14'

GLO survey A-9 W. between 19 & 30
76.64 ch. Intersect W. boundary
at post (no wit. noted on
page 137)

over

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" steel pin with rerod rusted to one side of it
Removed & replaced with std. 3/4" X 36" std. monument

And is accepted as a careful and faithful perpetuation of the position of the original corner.

Peer Group approved 12-14-99

Road traverse M-9-M-10 2643.20'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 36" std. Allegan Co. Monument
PK nail on top of guard post S13°E 19.66'
PK nail on top of guard post N43°W 29.57'
PK nail on top of guard post N66°W 62.76'
PK nail on top of guard post N42°E 24.88'
Spike on top guard post S50°W 26.68'

APPROVED REMONUMENTATION CORNER

P.A. 345 OF 1990

ALLEGAN COUNTY

DATE APPROVED DEC. 14, 1999

COUNTY REP. [Signature]

Signed by

[Signature]

Date 12-10-99

Surveyor's Michigan License No. 21572



M-9 Part "A" continued

1. Oct. 1869 - Survey by E. Strong DS
NE Cor. Sec. 25 - 14 X 11 X 7 - stone
2. old maps
1/2 mile to N - 40.1 ch.
1/2 mile to S - 40.09 Ch.
3. 1956 MDOT - 1" iron
CP NW 42.8'
G. pole NE 57.4'
CP pole SE 60.5'
Steel fe. post SW 34.3'
18" oak NE 45.1'
4. MDOT map 1956
Shows corner as common with T4N, R11W
1/2 to North - 2664.12'
1/2 to South - 2652.54'
5. SW Cor. Sec. 19 - Leighton
Ratekin - 1978 Not noted what was found
Guard rail post SW 26.73'
Guard rail post SSE 19.74'
Guard rail post NE 24.87'
Guard rail post NW 29.52'
6. Recorded surveys by MVK
Liber 992, Page 750 and Liber 849, Page 445
Same as LCRC #L-3, Page 294
7. MVK 1979, LCRC #L-3, Page 294
Part B Fd. 1" solid rod on C/L gravel
Part C
Nail in guard post SSE 20.05'
Nail in guard post NE 25.31'
Nail in guard post WNW 62.00'
8. Holland Eng.
Part B Rd. 1" solid Rod on C/L gravel
Part C
Nail in guard post SSE 20.05'
Nail in guard post NE 25.31'
Nail in guard post WNW 62.00'
9. Recorded survey, Jonker, 1984
1" steel pin
PK Nail top guard post S13°E 19.66'
PK nail top guard post N43°W 29.57'
spk. top guard post S50°W 26.68'
PK nail top guard post N66°W 62.76'
PK nail top guard post N42°E 24.88'
10. Wightman Moored 1994
used corner - no witnesses

RECEIVED
JULY 8
1999

MAR 07 2000

SECTION

Out
Out
Out
Out
Out

Check OK
Check OK
Check OK
Check OK
Check OK

Check OK
Check OK
Check OK

Check OK
Check OK
Check OK

Check OK
Check OK
Check OK
Check OK
Check OK

A-9

1. Old wit. map - calls for
stone & gov. wit.

2. LCRC # 3-103, MVK 1976

Part B - fd. 1" iron

Part C -

Nail on top guard rail post SW 26.73'

Nail on top guard rail post SSE 19.74'

Nail on top guard rail post NE 29.87' Nail on top guard rail post NW 29.52'

3. Recorded survey, MVK L.899, P. 85
Same as LCRC 1976

4. Recorded survey by MVK 1976
same wit. as LCRC

5. Survey by Ragekin 1978
Stone & gov. wit.

LIBRARY / FILE 3333