

JAN 27 2000

Liber 00003 Page 0083

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

ANTRIM COUNTY MI.
Register of Deeds
Recorded

For corners in

Helena Twp.

Antrim

(County)

Located In:

Corner Code #

12-14-1999 13:40:04

Wanda R. Conway
REGISTER OF DEEDS

1. Public Land Survey	22	T29N R8W	I-9
		T___ R___	_____
		T___ R___	_____
		T___ R___	_____
2. Property Controlling in Section	S___	T___ R___	_____
	S___	T___ R___	_____
3. Miscellaneous Property in Sec.	S___	T___ R___	_____
	S___	T___ R___	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Terry B. Smith, in a field survey on 11-22, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO Circa 1850 -- no evidence found
7-25-92 restoration by C. E. Ostling by dbl. Proration
Notes indicate that a pipe appears in the center line intersection after restoration.
9-26-87 LCRC B. Jones found 3/4" pipe
8-25-94 LCRC A. Lennox found 1/2" bar by #12026

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found both corners per above descriptions. Peer group presentation and discussion found that double proration based upon previous evidence by Church is a faithful perpetuation of GLO corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-9 found 1/2"x18" bar established by #12026
set Antrim County Monument
24" Maple S60W 33.48
24" Maple N45W 36.10
24" Maple S40E 49.90
1/2" Pipe N34E 16.08
UP N45E 47.88

Ratified by Peer Group
In accordance with
P.O. 345
Antrim Co. Chairman

Arthur L. Lennox

Arthur L. Lennox
Nov. 10, 1999



Signed by Terry B. Smith
Surveyor's Michigan License No. 25873

Date 12-14-1999