

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Antrim (County)	Located In	Corner Code #
1. Public Land Survey	T 31N R 6W	K-9
	T 31N R 6W	K-10
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Section	S T R	
	S T R	
4. Lot No: _____	Recorded Plat: _____	
5. Private Claims: _____		

Register of Deeds Stamp & File Number

I, Carl T. Kiiskila, in a field survey on December 6, 2006, do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-9 G.L.O. 1856 E.D. Atwater set post for corner of sections 23, 24, 25 & 26.

Wit: Elm 14" N39 1/4°E 29 links
Sugar 12 S74°W 30 links

K-10 G.L.O. 1856 E.D. Atwater set quarter section post

Wit: Sugar 10 N49 1/4°W 32 links
Beech S20 1/2°E 49 links

Liber 2, page 2 1984 Beryl Jones R.L.S.#23514 found 1" iron for corner. Wit: N40°W P. Pole 54.48'

N61°E H. Horn 51.70'

2006 John Ferguson R.L.S. #24595 certificate of survey shows he found a 1 1/4" pipe for corner.

Wit: 10" Maple N80°W 19.21'
10" Maple N18°W 25.81'
8" Maple East 9.55'
10" Cedar S10°E 27.47'

John Ferguson R.L.S. #24595 certificate of survey shows he found a railroad spike for the corner.

Wit: Utility Pole N26°W 54.90'
4" Pine S25°W 51.88'
14" Beech S20°E 38.82'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-9 Found Tee iron fitting J. Ferguson's survey in section 24.

K-10 Found 1 1/4" pipe as witnessed by J. Ferguson.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9 Added P.S. cap #33981 to found Tee iron

Wit: 16" Spruce N54°W 54.58'
5" S. Pine S47°W 69.45'
7" Elm S38°E 51.77'
15" Dead Beech S18°E 37.95'
P. Pole S54°W 54.58'
Centerline of E-W road
East edge of Road South

K-10 Added P.S. cap #33981 to found 1 1/4" pipe

Wit: 10" Maple N14°W 25.79'
10" Maple N83°W 19.20'
16" Maple S09°W 27.27'
8" Maple N89°E 9.47'

Signed by:

Carl T. Kiiskila

Date:

2-15-07

Surveyor's Michigan License No.:

33981

