

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 47N R 33W	MC West of F5
	T 47N R 33W	G5
	T	
2. Property Controlling in Section	S T	R
	S T	R
	S T	R
3. Miscellaneous Property in Sec.	S T	R
	S T	R
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on MC 08/22/2011 G5 08/22/2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC West of F5) Meander corner on the east side of Drummond Lake on the line between Sections 9 and 16. 1852 - Established by Deputy Surveyor Francis Houck S89 deg. 54'W 69.31 chains from Section corner 9-10-15-16, and 29.355 chains from the 1/4 corner between Sections 9 and 16. Set post. Tamarack 10 N77E 19 links. No other tree near.

(G5) Corner common to Sections 9-10-15-16. 1852 - Established by Deputy Surveyor Francis Houck. BT's: Spruce 12 N72E 30 links, Spruce 10 S61W 36 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC) The original post and accessories were not recovered. Reestablished the position for the corner on the extension of a line between G5 and F5 and at record distance 29.355 chains (1937.43') west of Quarter corner F5. The true mean bearing and distance along the Section line from G5 to the MC is S89 deg. 39'28"W 4570.63 feet. The position for the corner was monumented with a WITNESS CORNER 110.00' east of the record MC position, on the Section line.

(G5) The original post and accessories were not recovered. Found a 1.5" ID iron pipe, projecting about 2 ft., with metal location poster dating to at least 1978 facing on an adjacent 10" B.Spruce. Distances north and west to adjacent corners G3 and F5 check reasonably well with the original record. I accepted the pipe as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap 110.00' east of the MC position and on the Sec. line for a WITNESS CORNER.
Set measuring nail with MDNR tag in the side of:
6" Spruce North 22.9' mrkd "WC BT"
15" Maple N72E 49.4' do
7" Balsam S71E 12.8' do
2" Balsam S82W 10.3' " X X "
Set sq'd cedar post adjacent.
Bearings are magnetic.

(G5) Found 1.5" ID iron pipe.
Set measuring nail with MDNR tag in the side of:
10" B.Spruce S54E 25.2' mrkd "S15 NBT"
10" B.Spruce S20W 7.6' "S16 NBT" w/poster
10" B.Spruce S70W 28.8' do
8" Spruce N44W 18.1' "S9 NBT"
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 04/26/2012

For the Michigan Department of Natural Resources, Forest Resources Division

