

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: December 7, 2017

For corner(s) in: Baraga County

Original Public Land Survey Corner

Corner Code

S T R
S T R
S T R
S T R

Property Corner

1/16 Corner Code

a. S 16 T 48N R 31W 15 (GCDB 320400)
a. S 21 T 48N R 31W 1 (GCDB 320400)
b. S 16 T 48N R 31W 16 (GCDB 360400)
b. S 21 T 48N R 31W 2 (GCDB 360400)

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner History

a. West 1/16 corner between Sections 16 and 21. Not established in the original survey. Corner indicated as monumented (by symbol) on sketch of Section 21 T48N-R31W by "R.A.B." [presumably R.A.Brotherton] dated Oct. 1934. Corner also indicated as monumented (by symbol) at the intersection of fence lines north and west on survey of "Shusta and Ollila Parcels" January 27, 1996 by L.J.Bussone PS. Also described on a survey by T.A.Goodwin PS, dated Jan. 16, 2007 as "1/16th corner and NE corner of Gov't Lot 6, Section 21, T48N,R31W. Found 5/8" iron pin witnessed by: Tamarack 9" N48°E, 11.87', Tamarack 6" S41°E 5.80', Spruce 7" S61°W 19.04', Spruce 4" N58°W 20.25'." Survey is North Country Engineering Job No. 06-1097.

b. East 1/16 corner between Sections 16 and 21. Not established in the original survey. Found no subsequent record.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a. Found a 5/8" iron pin at the end of an old fence to the north, conforming to the T.A.Goodwin survey of 2007. The 2007 witnesses were found to be measuring nails set in zinc washers. Located 5 irons on the East line of Gov't Lot 6, set during the 2007 survey and appearing on the 2007 drawing and found this pin to be in accord with the location shown on the 2007 survey. Accepted the 5/8" iron pin as a careful and faithful determination of the position of the corner.

b. The position for the corner was found unmonumented. Established the position for the corner midway and on the Section line between Quarter corner F07 (as perpetuated by Brandon Juntunen PS in 2017) 1322.63' west and Section corner G07 1322.63' east.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a. Found 5/8" iron pin.
Found measuring nail with washer in the side of:
9" Tamarack N48°E 11.87'
6" Tamarack S41°E 5.80'
7" Spruce S61°W 19.04'
4" Spruce N58°W 20.25'
E= 7908350.90 N= 196994.39

b. Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
2" B.Ash N46°E 6.85' mrkd "1/16S BT"
Twin 3" B.Ash S10°E 24.3' do
11" Maple S25°W 27.65' do
3" B.Ash S62°W 9.75' do
Set sq'd cedar post adjacent.
E= 7909158.21 N= 196985.53

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.09

Stephan J. Szyszkoski

02/05/2018



Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908