

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 48N R 31W	G6
	T 48N R 31W	H3
	T	
2. Property Controlling in Section	S T	R
	S T	R
	S T	R
3. Miscellaneous Property in Sec.	S T	R
	S T	R
4. Lot No.	Recorded Plat	
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on G6 05/18/2010 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G6) Quarter corner common to Section 15 and 16. 1984 - Reestablished by Alan K. Pierce RLS midway  
and on the Section line between Section corners north and south. Mr. Pierce was not able to monument  
the corner position but set a reference monument, a 1/2" x 18" capped rebar S58 deg. 14'45"W 0.74'  
from the true corner position. Witnesses to the reference monument (called a 'witness corner' in the  
record, dated 1985) - PK nail in the following: 12" Oak N60W 16.00', 8" Y.Birch N42E 5.17', 10"  
Y.Birch S72E 21.98', 6" Maple S41W 4.22'. See LCR Liber 4, Page 89.

(H3) Quarter corner common to Sections 3 and 10. 1848 - Established by Wells Burt Deputy Surveyor  
midway and on the Section line between Section corners 39.98 chains east and west. Set Spruce post.  
Spruce 7 N74W 40 links, Spruce 6 S34W 41 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G6) The 1984 monument was found in good condition and at record bearing and distance from the  
accessories. The two 1984 Y.Birch BTs are now down and rotting on the ground. The Maple and Oak BTs  
are in good condition with overgrown blazes. Accepted the 1984 position as a careful and faithful  
reestablishment of the position of the original corner.

(H3) The original post and accessories were not recovered. Found no acceptable evidence of the  
position of the original corner on the ground. Reestablished the corner position midway and on the  
Section line between Section corners 2623.08' east and west, proportionate to the original record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G6) Fd. 1/2" capped rebar reference monument  
as recorded in L4 P89. Set measuring nail with  
MDNR tag in the side of:  
3" Sugar N06W 8.4' mrkd "WC BT"  
5" twin Sugar N59E 20.25' do  
Found the 1984 accessories:  
7" Maple S49W 4.22' PK nail  
14" Oak N56W 16.0' do  
Bearings are magnetic.

(H3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
4" B.Spruce N20E 5.05' mrkd "1/4S NBT"  
3" B.Spruce S49E 5.45' do  
3" B.Spruce S83W 3.2' do  
4" Tamarack N30W 7.2' do  
Set sq'd B.Spruce post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/07/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

