

LAND CORNER RECORDATION CERTIFICATE
Filling Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 9 T 48N R 32W S _____ T _____ R _____ S 9 T 48N R 32W	6 (GCDB 360560) 9
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 360540)
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/03/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(6-Sec. 9) Northeast 1/16 corner, Section 9. Not previously monumented.

(9-Sec. 9) Center-East 1/16 corner, Section 9. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 9) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

(9-Sec. 9) Established the position for the corner midway and on a straight line between Quarter
corner 1324.02' east and the intersection of 1/4 lines of Sec. 9 1324.02' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
2" Spruce S40°W 30.95' mrkd "1/16S BT"
2" Tamarack S84°W 76.10' do
5" Spruce N75°W 81.05' do
4" Tamarack N44°W 75.25' do
Set sq'd cedar post adjacent.
E= 7899653.684 N= 199955.275

(9) Set 1"IDx10" I.pipe over 5/8"x8" rebar drilled
and grouted into rock, capped with a 2" dia. alum.
MDNR cap. Set measuring nail with MDNR tag in the
side of:
5" Balsam N29°E 10.35' mrkd "1/16S BT"
6" Balsam S70°E 10.25' do
7" Maple S09°E 14.35' do
9" Maple N81°W 5.6' do
Set sq'd cedar post adjacent.
E= 7899646.360 N= 199557.992

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID RL1468: N= 199449.721 m. E= 7900600.011 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/18/2014

For the Michigan Department of Natural Resources, Forest Resources Division