

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga
(County)

Located In:

Corner Code #

1. Public Land Survey T 48N R 33W MC #1 (Meander
T R Corner on East shore
T R of King Lake between
S T Sections 26 & 35)
S T
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File
Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Stephan J. Szyszkoski, in a field survey on July 11, 20 05 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Meander Corner on East shore of King Lake between Sections 26 and 35. 1851 - Established by Francis Houck: West Corrected between Sections 26 & 35 ...39.94 Set Qr. post ...69.76 intersect Lake and set Meander Corner. W.Pine 12 N55°E 6 links, Y.Pine 12 S34°W 17 links. ...79.88 Corner in Lake. S 89°45'W Corrected between Sections 27 and 34, 34.46 Set Meander Post. 1970 - Remonumented by A.O.Enger RLS and recorded in 1973 as follows: "Original meander post or its accessories not found. Found a 1"IDx43" iron pipe on shore of King Lake, purporting to be the M.C. Accepted monument as found, as it, in conjunction with J9 and J11, is reasonably consistent with the record of the original survey. All corners have been long used in adjacent property descriptions. Set 1"ID iron pipe with 4" aluminum cap. Witnesses: Red Pine 12" South 8.7' "MC,NBT"; Red Pine 10 N86°E 19.4' "MC,NBT". Mr. Enger's survey drawing gives the true bearing and distance from J11 to this corner as N 89°25'20"W 1975.21'. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered the 1970 MDNR monument in good condition and at substantial record bearing and distance from the 1970 witness trees, both in good condition with blazes now overgrown. From Mr. Enger's 1970 perpetuation of corner J11 to this monument, I observed a true bearing and distance of N 89°29'03"W (GLO index-corrected record N 89°38'W) 1972.29' (GLO record 1968.1'). I observed a distance of 2945.23' (GLO record 2942.3') from this MC, across the lake, to the reestablished MC on the west shore of King Lake. I note that this close agreement with the record is consistent with the findings of my retracement of 5 sections in this part of the township and I accept the 1970 monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1"ID iron pipe with 4" aluminum
MDNR cap. Set measuring nails in:
14" R.Pine N89°E 19.6' *
13" R.Pine S07°W 10.9' *
8" R.Pine S39°W 21.4' mrkd "MC NBT"
15" R.Pine N40°E 3.2' do
Set sq'd cedar post adjacent. Bearings
are magnetic. Distances are to nail
with tag.

* denotes 1970 witness tree of record.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 7/27/05

For the Michigan Department of Natural Resources, Office of Land and Facilities