

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 11 T 49N R 32W	16
	S 11 T 49N R 32W	J4
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on J4 12/06/2010 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 11) East 1/16 corner between Sections 11 and 14. Not established in the original survey. Norman T. Thompson RLS set post here circa 1942. BT Sugar 7" N80E 5.5'.

(J4) Center of Section 11. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 11) The 1942 Thompson post and BT were not recovered. Established the corner midway and on the Section line between Quarter corner 1326.25' west and Section corner 1326.25' east.

(J4) Established the corner at the intersection of straight lines connecting opposite 1/4 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
10" Sugar N61E 7.2' mrkd "1/16S BT"  
12" Sugar S39E 15.25' do  
7" Sugar S37W 11.85' do  
14" Spruce N83W 15.55' do  
Set sq'd Cedar post adjacent.  
Bearings are magnetic.

(J4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
15" Cedar N50E 15.8' mrkd "C1/4 BT"  
6" Maple S61E 8.95' do  
14" Cedar S65W 20.7' do  
7" Spruce N46W 22.95' do  
Set sq'd Cedar post adjacent.  
Bearings are magnetic.

Signed by

Surveyor's Michigan License No.

33986

Date

07/27/2011

For the Michigan Department of Natural Resources, Forest Management Division



16647

16655

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

Revised Oct., 1995