

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 11 T 49N R 32W	6
	S 11 T 49N R 32W	7
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	16		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 6 05/24/2011 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(6-Sec. 11) Northeast 1/16 corner, Section 11. Not established in the original survey.

(7-Sec. 11) North 1/16 corner between Sections 11 and 12. 1942 - Norman T. Thompson RLS set post at corner and made Y.Birch BT 14" N50E 3.2'. 1975 - Mead Corp. foresters Ervast and Lazzari found the 1942 post point and BT and perpetuated the position with a 1"IDx4 ft. iron pipe and made two new BTs: Balsam 9.1" S48E 8.0', Sugar 10.9" N36E 21.0'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 11) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

(7-Sec. 11) Found a 1"ID iron pipe at record bearing and distance from the 1975 Sugar BT and from the remains of the 1942 Y.Birch BT, now a rotted stump. The pipe is 1298.01' north of Quarter corner K4 and 1297.91' south of Section corner K3, and 0.6' east of a straight line between them. I accept the pipe as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Sugar N49E 24.9' mrkd "1/16S BT"
9" Sugar S27E 14.85' do
6" Sugar S23W 19.5' do
6" Sugar N36W 17.65' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(7) Found 1"ID I.pipe.
Set measuring nail with MDNR tag in the side of:
12" Sugar N43E 21.0' mrkd "1/16S BT"
5" Spruce S84E 16.45' do
5" B.Spruce S08E 9.65' do
5" Balsam N34W 2.95' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/27/2011

For the Michigan Department of Natural Resources, Forest Management Division



16668

16654