

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 11 T 49N R 32W	2
	S 12 T 49N R 32W	1/64 E. of #3
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 64th 05/24/2011 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(2-Sec. 11) East 1/16 corner between Sections 2 and 11. 1942 - Established by Norman T. Thompson RLS. Set balsam post and BT Cedar 10" S85E 7.7'. 1975 - Mead Corp. foresters Ervast and Lazzari found the Thompson balsam post point and BT and perpetuated the position with a 1.25" x 3 ft. iron pipe, and made new BTs: Maple 5.5" S84W 19.2', Maple 5.9" N11E 16.0'.

(1/64 E. of #3) C-W-NW 1/64 corner, Section 12, being the SE corner of the W1/2 of the NW1/4 of the NW1/4 of Section 12. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(2-Sec. 11) Found a 1.25" ID iron pipe at record bearing and distance from all three BTs noted above. Distance east to Section corner is 1341.62'. Distance west to 1/4 corner is 1337.18'. The pipe is 1.4' North of a straight line between them. I accept the pipe as a careful and faithful determination of the position of the corner.

(1/64 E. of #3) Established the corner midway and on a straight line between 1/16 corner #3 651.94' west and unmonumented 1/16 corner #4 651.94' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(2) Fd. 1.25" ID I. pipe
Set measuring nail with MDNR tag in the side of:
12" Cedar S72E 8.35' old scribing 1942 BT
7" twin Maple N13E 16.1' mrkd "1/16S BT"
7" Maple N88W 19.0' do
6" Sugar S17W 7.45' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(1/64) Set 1" ID x 32" I. pipe with 4" alum. MDNR cap
Set measuring nail with MDNR tag in the side of:
10" Sugar N14W 14.5' mrkd "1/64S BT"
6" Sugar N59E 15.8' do
12" Y. Birch S17E 13.5' do
5" Sugar S32W 6.0' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/27/2011

For the Michigan Department of Natural Resources, Forest Management Division



16653

16667

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, 1971

Revised Nov. 14, 1975

Revised Jan., 1983

Revised Oct., 1995