

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 32W T 49N R 32W T T	M5 I2
2. Property Controlling in Section	S S S S	T T T T
3. Miscellaneous Property in Sec.	S S S S	T T T T
4. Lot No. _____, Recorded Plat		
5. Private Claims		

M5 12/01/2010

I2 05/31/2011

I, Stephan J. Szyszkoski, in a field survey on _____ do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M5) Corner common to Sections 12-13 T49N-R32W and Sections 7-18 T49N-R31W. 1846 - Established by
Wm.A.Burt Deputy Surveyor. Set Spruce post. Spruce 7" N52 1/2E 19 links, Spruce 9" S28W 34 links.
Additional BTs by Guy Carleton Deputy Surveyor, 1852: Y.Birch 8" S84E 49 links, Spruce 10" N55W 76
links. Found no subsequent record.

(I2) Quarter corner common to Sections 2 and 3. 1852 - Established by Guy Carleton Deputy Surveyor
on the Section line between Section corners 40.00 chains south and 39.74 chains north. Set post.
Yellow Birch 6" N46W 20 links, Spruce 8" N07E 35 links. 1942 - Norman T. Thompson RLS did not find
the original corner or accessories, ran the section line with a "pocket compass" and "... set 4"
cedar picket for 1/4. This to be moved 8' north and 12 paces west".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M5) The original post and accessories were not recovered. At the intersection of blue paint lines N-
S and E-W, found a 1"ID I.pipe projecting 12" a.g., not of record. Accepted same as the best
available evidence of the position of the original corner. The true bearing and distance to M3 from
this corner was found to be N0 deg. 10'45"E (GLO = North) 5240.33' (GLO=5280'). A portion of this
line runs over Fisher Lake.

(I2) The original post and accessories were not recovered. Found no acceptable evidence of the
position of the original corner on the ground. Reestablished the corner on the Section line between
Section corners 2626.72' south and 2609.65' north, being proportionate to the original record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M5) Found 1"ID Iron pipe projecting 12" a.g.
Set measuring nail with MDNR tag in the side of:
5" Y.Birch N02E 21.8' mrkd "S7 NBT"
6" Maple S86E 17.6' "S18 NBT"
4" Cedar S50E 15.35' do
6" B.Spruce S07W 11.55' "S13 NBT"
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(I2) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
6" Maple N09E 17.8' mrkd "1/4S NBT"
10" Maple S86E 1.8' do
6" Y.Birch South 27.15' do
10" Maple N80W 13.05' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/27/2011

For the Michigan Department of Natural Resources, Forest Management Division

