

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 32W D13 T 48N R 32W D1 T R (Same Corner)	
2. Property Controlling in Section	S T R S T R S T R	
3. Miscellaneous Property in Sec.	S T R S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	3		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 11/12/2008 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Quarter corner common to Section 32 T49N-R32W and Section 5 T48N-R32W. 1846 - Established by Austin  
Burt Deputy Surveyor midway and on the Township line between Section corners 40.00 chains east and  
west. Set Fir post. Fir 7" N42E 34 links, Fir 8" N7W 49 links. 1988 - Monumented by K.L.Sackett  
RLS midway between Section corners 1/2 mile east and west. Set Witness Corner on the N-S 1/4 line of  
Section 32 36.5' north of the corner position. Set 1"x32" I.pipe with 4" alum. MDNR cap. 8" Balsam  
S85W 19.8', 5" Balsam N02W 17.3', 7" Balsam N31E 14.0'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The original corner and accessories were not recovered. The position for the corner now falls in the  
Sturgeon River. Did not accept the 1988 position for the corner. The 1988 position was determined  
using an erroneous 1978 position for corner E13 which was not accepted by the undersigned. The 1978  
E13 position is N39W 99.3' from the E13 position used by the undersigned to reestablish D13 herein  
described. I reestablished the corner midway and on the Township line between monumented Section  
corners C13 and D13 2638.03' east and west, being proportionate to the original record. From the  
position thus established, the 1988 Witness Corner was found 74.5' north and 31.6' west. The Quarter  
corner position is not monumented. Set a Witness Corner on the N-S 1/4 line of Section 32 75.00' N00  
deg. 34'18"E (true bearing) from the position for the Quarter corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1"IDx32" I.pipe with 4" alum. MDNR cap for  
a Witness Corner, 75.00' northerly of the Quarter  
corner position and on the N-S 1/4 line of  
Sec. 32 T49N-R32W. Set measuring nail with  
MDNR tag in the side of:  
9" Balsam West 51.4' 1988 scribing visible  
9" Balsam N60W 27.0' mrkd "WC BT"  
6" Balsam N16W 16.8' do  
4" Balsam N08E 25.95' do  
Bearings are magnetic.



Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 01/12/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995