

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 28 T 49N R 34W	8
	S 32 T 49N R 34W	12
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 12/11/12 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8) **West 1/16 corner, Section 28.** 1975 - Established by K.L.Sackett RLS. Set 1"IDx36" iron pipe with 4"
aluminum cap. 4" J.Pine N35E 6.5', 14" W.Pine N50W 37.7'.

(12) **South 1/16 corner, Section 32.** Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8) Found the 1975 monument in good condition and at record bearing and distance from the 1975 BT
W.Pine, now 18" DBH with overgrown blazes. The monument is substantially midway and on a straight
line between Quarter corner E10 and the Center of Section 28 and I accept same as a careful and
faithful establishment of the position of the corner.

(12) Established the position for the corner midway and on a straight line between Quarter corner
1318.08' south and Center of Section 32 1318.08' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Found 1"ID I.pipe with 4" alum. State of
Michigan cap. Set measuring nail with MDNR tag in
the side of:
18" W.Pine N43°W 38.2' old blazes (1975 BT)
7" B.Spruce N18°E 9.35' mrkd "1/16S BT"
6" W.Pine S77°E 8.2' do
7" B.Spruce S16°E 4.8' do
Set sq'd cedar post adjacent.
E=7879811.906 N=204738.977

(12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" J.Pine North 20.85' mrkd "1/16S BT"
8" B.Spruce N71°E 8.1' do
4" B.Spruce S13°E 24.3' do
6" J.Pine S52°W 36.05' do
Set sq'd cedar post adjacent.
E=7878554.500 N=202755.842

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

