

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 34W	G13
	T R	
	T R	
2. Property Controlling in Section	S 28 T 49N R 34W	SMC E10-8
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on G13 06/04/13
SMC 04/24/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(SMC E10-8) Special Meander Corner on the East shore of Big Lake and on the E-W 1/4 line of Section
28, between Government Lots 2 and 3. Not previously monumented.

(G13) Corner common to Sections 33-34 T49N-R34W and Sections 3-4 T48N-R34W. 1846 - Established by
Wm. Burt Deputy Surveyor. Set tamarack post. Tamarack 6" N29°E 20 links, Cedar 10" N65°W 8 links.
Additional witnesses taken in 1853 by F.Colman: Tamarack 5" S51°E 21 links, Tamarack 5" S69°W 41
links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(SMC E10-8) Established the position for the corner at the intersection of the E-W 1/4 line of
Section 28, on a straight line between monumented corners E10 and 1/16 cor. #8 with the GLO meander
of Big Lake as given in the original U.S. Field Notes of this township, said meander having been
adjusted using the Compass Rule. The position for the corner falls 592.22' West of 1/16 corner #8,
Sec. 28.

(G13) Remonumented the corner at the position of post point found at record bearing and distance
from the remains of three of the BTs of record: Tam. 6" N29°E 20 links, now woody debris; Tam. 5"
S69°W 41 links, now a 10" stump (previously windthrown); Cedar 10" N65°W 8 links, now a 12" stump
(previously windthrown). No markings found. Accepted the post point as the best available evidence
of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(SMC E10-8) Set 1"IDx32" I.pipe with 4" alum. MDNR
cap. Set measuring nail with MDNR tag in the side
of:

5" W.Pine N10°W 3.55' mrkd "SMC BT"
7" J.Pine S77°E 25.0' do
8" J.Pine South 6.55' do
9" J.Pine N53°W 29.75' do

Set sq'd cedar post adjacent.
E= 7879631.534 N= 204744.600

(G13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:

10" Tamarack N17°W 45.6' mrkd "S33 NBT"
6" Tamarack N29°E 21.2' "S34 NBT"
6" Tamarack S58°E 22.2' "S3 NBT"
5" Tamarack S70°W 20.5' "S4 NBT"

Set sq'd cedar post adjacent.
E= 7880952.493 N= 202304.885

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 08/06/2013

For the Michigan Department of Natural Resources, Forest Resources Division

