## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	_ Located In:	Corner Code #								
1. Public Land Survey	T 49N R 33W T R R 33W	M12 (GCDB 700140)								
2. Property Controlling in Section	S T R S T R S T R	(GCDB 640200)								
3. Miscellaneous Property in Sec.	S T R S T R		R	egister	of Dec	eds Star	mp & Fi	ile Nu	ımber	•
4. Lot No. , Red 5. Private Claims	corded Plat		A	вс			G H	_	J k	
3. Tittace Claims	M12 08	3/10/15	2	6	- 5	_  -	- 3-	$\bot$	2-	
above were in conformance with a instructions of the United States I a Court of Law and /or that the	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requir Department of the Interior, Bureau of Lorner points mentioned in lines 3, 4 and	red in the current manual of survey and Management or by a decree of d 5 above were in conformance with	6 -	7	-17-	9-16-	-10-		11	13
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:					-20-		1 22			24-
NOTE: Not more than 2 corn on this certificate,	ers, all in the same town and range	e, may be recorded	11 12	30	-29 -32	—28 —33—	34	+-	35	-2 <sup>5</sup>

A. Description of original monument and accessories and/or subsequent restoration:

(M12) Quarter corner common to Section 36 T49N-R33W and Section 31 T49N-R32W. 1846 - Established by Austin Burt, Deputy, midway and on the Range Line between Section corners 40.00 chains north and south. Set sugar post. Y.Birch 12" S64°E 24 links, Sugar 12" N88-1/2°W 25 links. Found no subsequent record.

(L11) Quarter corner common to Sections 25 and 36. 1852 - Established by Z.B.Searles, Deputy, midway and on the Section line between Section corners 40.36 chains east and west. Set post. Y.Birch 5" S36°E 38 links, Sugar 8" N23°W 26 links. 1945 - Notes of N.T.Thompson RLS state about the line between 25 and 36 "Run from W. cor. No 1/4 cor."

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (M12) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Range Line between Section corner 2613.62' north and Township corner 2613.62' south
- (L11) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2634.97' east and west.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.	(L11) Set 1"IDx28" I.pipe with 2"	alum MDNP can
Set measuring nail with MDNR tag in the side of:	Set measuring nail with MDNR tag	in the side of:
3" Spruce N08°W 10.3' mrkd "1/4S NBT"		"1/4S NBT"
15" Sugar N34°E 21.0' do	4" Sugar N68°E 7.55'	do
4" Sugar S83°E 25.4' do	13" Sugar S27°E 10.6'	do
15" Maple S37°E 23.6' do	11" Sugar S48°W 18.65'	do
Set sq'd cedar post adjacent.	Set sq'd cedar post adjacent.	
E= 7895370.179 N= 202816.886	E= 7894575.133 N= 203631.364	

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF