

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 33W T _____ R _____ T _____ R _____	I10 (GCDB 500240)
2. Property Controlling in Section	S 27 T 49N R 33W S _____ T _____ R _____ S _____ T _____ R _____	H10 (GCDB 440240)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on H10 07/22/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I10) Quarter corner common to Sections 26 and 27. 1852 - Established by Z.B.Searles, Deputy. Set post midway and on the Section line between Section corners 39.98 ch. north and south. Y.Birch 12" S73°W 25 links, Cedar 18" S24°E 8 links. 1944 - N.T.Thompson RLS states that he chained south from I9 2638.7' [note: this would be the record GLO distance -ss] to 1/4 corner and set cedar post with new BTs: Cedar 6" S80°E 10.0', Sugar 4" S45°W 22.8'.

(H10) Center of Section 27. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I10) The original post and accessories were not recovered. Found a 1"ID I.pipe projecting 2 ft. a.g. at record bearing and distance from the remaining 1944 NBT Cedar, now 13", in good condition. Distance to I9 was found to be 2625.41', distance south to monumented I11 was found to be 2653.85', and I10 is 4.36' east of a straight line between them. Accepted the monument as the position of the corner through it's long use as such.

(H10) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners. From the position thus established, there is a forester's approximate corner (tree with tag marked as such), with blue paint lines running from it to the east and south, S41°E 17 feet distant.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I10) Found a 1"ID I.pipe with flattened top. Set measuring nail with MDNR tag in the side of: 13" Cedar S80°E 10.4' old blazes (1944 NBT) 7" Y.Birch N25°W 8.6' mrkd "1/4S NBT" 8" Y.Birch N73°W 20.7' do 6" Y.Birch S45°W 18.55' do Set sq'd cedar post adjacent. E= 7892189.151 N= 204478.699

(H10) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 4" Sugar N21°W 18.0' mrkd "C1/4 BT" 3" Sugar S72°E 15.55' do 5" Sugar S23°E 21.95' do 5" Ironwood S65°W 14.2' do Set sq'd cedar post adjacent. E= 7891385.766 N= 204496.155

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/27/2015

For the Michigan Department of Natural Resources, Forest Resources Division

