

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 50N R 33W	D5
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Stephan J. Szyszkoski, in a field survey on 08/03/2011 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D5) Quarter corner common to Sections 8 and 17. 1849 - Established by Wm.Burt Deputy Surveyor  
midway and on the Section line between Section corners 40.21 chains east and west. Set cedar post.  
Y.Birch 10" N41E 21 links, Hemlock 20" S16E 9 links. Found no subsequent record. Norman T. Thompson  
RLS did survey work in this area in the 1940's for Ford Motor Company.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D5) The original post and accessories were not recovered. Found a 1" dia. hex drill rod, firmly  
set, substantially at record bearing and distance from Quarter corner B5 5286.98' westerly, at the  
intersection of blue painted lines north and east and conforming to cultivated field and cutting  
lines along the former Ford Motor Company lands south and west. I accepted the drill rod as the best  
available evidence of the position of the corner and used it to reestablish Section corner C5  
2650.47' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D5) Found 1" drill rod  
Set measuring nail with MDNR tag in the side of:  
8" Maple N37E 19.3' mrkd "1/4S NBT"  
7" Sugar N45E 22.15' do  
6" Sugar N83E 6.4' do  
4" Maple S89E 27.2' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.



Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/08/2011

For the Michigan Department of Natural Resources, Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995