

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 50N R 33W T 50N R 33W T R	C6 B7
2. Property Controlling in Section	S T R S T R S T R	
3. Miscellaneous Property in Sec.	S T R S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on C6 07/21/2011
B7 07/19/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C6) Quarter corner common to Sections 17 and 18. 1849 - Established by Wm.Burt Deputy Surveyor
midway and on the Section line between Section corners 40.00 chains north and south. Set Sugar post.
Y.Birch 12" S44E 26 links, Y.Birch 14" N67W 14 links.

(B7) Quarter corner common to Sections 18 and 19. 1849 - Established by Wm.Burt Deputy Surveyor on
the Section line between Section corners 40.00 chains east and 35.70 chains west. Set Maple post.
Sugar 16" S70E 4 links, Sugar 4" N26W 25 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C6) The original post and accessories were not recovered. Found no acceptable evidence of the
position of the original corner on the ground. Reestablished the corner midway and on the Section
line between Section corners 2630.23' north and south, proportionate to the original record. From
the corner thus established, I found a squared post N09W 14 ft. distant, for a forester's approximate
corner.

(B7) The original post and accessories were not recovered. Found no acceptable evidence of the
position of the original corner on the ground. Reestablished the position for the corner on the
Section line between Section corners 2628.75' east and 2346.16' west, proportionate to the original
record. From the position thus established, I found a steel fence post in a rock mound for an
approximate corner S83W 35 ft. distant.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Sugar N29E 12.4' mrkd "1/4S NBT"
15" Hemlock S57E 29.85' do
11" Sugar S38W 7.1' do
11" Sugar N17W 8.5' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(B7) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
made firm in a mound of rock.
Set measuring nail with MDNR tag in the side of:
14" Sugar N37E 14.55' mrkd "1/4S NBT"
14" Hemlock S39E 23.2' do
6" Sugar S07W 11.0' do
12" Sugar N51W 12.5' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/24/2011

For the Michigan Department of Natural Resources, Forest Management Division

