

45

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Baraga

(County)

Located In:

Corner Code #

- | | | | |
|------------------------------------|------|-------|----------|
| 1. Public Land Survey | T | R | |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling in Section | S 20 | T 50W | R 34W 13 |
| | S 20 | T 50W | R 34W 16 |
| 3. Miscellaneous Property in Sec. | S | T | R |
| | S | T | R |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Stephan J. Szyszkoski, in a field survey on 16 August 08, 1995, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(13-Sec. 20) Southeast 1/16 corner, Section 20. corner not established in the original survey. Found no subsequent record.
(16-Sec. 20) East 1/16 corner between Sections 20-29. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(13-Sec. 20) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite 1/16 corners. At the position for the corner, I placed a 1" 10x32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped.
(16-Sec. 20) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a straight line between Section Corner 1323.55' east and Quarter corner 1323.55' west. At the position for the corner, I placed a 1" 10x32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(13) Set 1" pipe with 4" MDNR cap.	(16) Set 1" pipe with 4" MDNR cap.
Blazed and scribed the following bearing trees:	Blazed and scribed the following bearing trees:
12" W. Pine N08E 24.7' 1/16S BT"	19" Red Oak N62E 9.6' 1/16 NBT"
12" Maple S18E 40.6' 1/16S BT"	6" Db1 Maple S51E 15.5' 1/16 NBT"
6" Maple S75W 45.4' 1/16S BT"	12" Maple S83W 20.2' 1/16 NBT"
9" Maple N62W 21.2' 1/16S BT"	10" Spruce N52W 30.4' 1/16 NBT"
Bearings are Magnetic. Placed a squared 3" Maple post adjacent.	Bearings are Magnetic.



Signed by Stephan J. Szyszkoski Date 9-6-95
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources - Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1975
REVISED JAN. 1983