

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 50N R 34W	A6
	T 50N R 34W	A9
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/23/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A6) Quarter corner common to Section 18 T50N-R34W and Section 13 T50N-R35W. 1961 - Billy D. Buckler RLS reestablished the corner position by proportionate measurement along the township line between corners A5 and A8. Set 1" pipe with 4" aluminum cap. 6" W.Spruce S63°E 71 links, 5" Aspen N05°W 16.5 links. 1984 - the 1961 monument was recovered and accepted by R.L.Drahn RLS, who noted that the "correct corner position was found marked...on line and at midpoint between section corner to the north and south". He made new witnesses: 5" Red Maple N02°E 51.75', 7" Spruce S79°E 16.96', 10" R.Pine S51°W 46.62', steel sign post S59°W 1.65'.

(A9) Corner common to Sections 19-30 T50N-R34W and Sections 24-25 T50N-R35W. 1961 - Reestablished by Billy D. Buckler RLS by single proportionate measurement along the Range line between A8 and A11. Set 1" pipe with 4" brass cap. 16" R.Pine N30°W 140 links, 6" Aspen N39°E 25 links, 6" Aspen S40°E 30 links. 1984 - R.L.Drahn RLS found and accepted the 1961 monument. His new witnesses: 8" Aspen N80°W 6.0', 8" Aspen S50°E 24.2', 8" Aspen S10°E 19.0'. See L.4 of LCR, P.4.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A6) Found the 1961 monument in good condition and at record bearing and distance from the 1984 accessories: 5" Red Maple N02°E, steel sign post S59°W, and 10" W.Pine S51°W (rec. as R.Pine). The position monumented is N46°W 4.4' from the proportionate position between A5 and A8 and I accept the monument as a careful and faithful reestablishment of the position of the original corner. The quoted statement from the 1984 record, referenced above, is not correct, the 1961 position of A7 being erroneous.

(A9) Found the 1961 monument in good condition and at substantial record bearing and distance from the 1961 NBT R.Pine, in good condition, and from the 1984 NBTs Aspen S50°E (rec=24.2', M=22.0'), Aspen S10°E, and steel sign post. The position monumented is N35°E 3.0' from the proportionate position between A11 and A8 and I accept the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A6) Found 1"ID I.pipe with 4" MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
7" Maple N02°E 51.75' overgrown blazes (1984 NBT)
21" W.Pine S49°W 46.62' do do
6" Balsam N81°E 17.6' mrkd "1/4S NBT"
4" Balsam S15°E 5.6' do
steel sign post S47°W 1.65'
E= 7876568.561 N= 217601.731

(A9) Fd. 1"ID I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
21" R.Pine N23°W 93.35' old blazes (1961 NBT)
12" Aspen S49°E 22.0' do (1984 NBT)
11" Aspen S10°E 19.0' do do
8" Balsam S62°W 14.9' mrkd "S25 NBT"
steel sign post S34°W 2.0'
E= 7876512.216 N= 215196.251

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=NGS PID DI1837: N= 221257.624 m. E= 7884435.168 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/02/2013

For the Michigan Department of Natural Resources, Forest Resources Division

