## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	_ Located In:	Corner Code #	
1. Public Land Survey	T 50N R 34W	K7 (GCDB 600400)	
2. Property Controlling in Section	T 50N R 34W S T R S T R S T R	(GCDB 440300)	
3. Miscellaneous Property in Sec.	S T R S T R		Paristra of Paristra Original Assets
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number  1 A B C D E F G H I J K L N
	K7 10	0/22/15	2 - 6 5 4 3 2 1 -
above were in conformance with a instructions of the United States I	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requir Department of the Interior, Bureau of L	red in the current manual of survey and Management or by a decree of	,5
the rules of the Michigan Board re-established, monumented, recover	corner points mentioned in lines 3, 4 and do of Land Surveyors or by a Decree ered, found as expressed below:	of a Court of Law; established,	8 19 20 21 22 23 24
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town and range	e, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original m	onliment and accessories and/or	subsequent restoration.	13

- on of original monument and accessories and/or subsequent restoration:
- (K7) Corner common to Sections 13-14-23-24. 1849 Established by Wm. Burt, Deputy. Set Sugar post. Y.Birch 15" N67°W 27 links, Cedar 12" S63°E 36 links. 1976 - A.O.Enger, RLS found and accepted a 1"ID Iron pipe during a retracement survey in this township. The pipe was not subsequently witnessed or recorded. Mr. Enger monumented corners J7 and I7, to the west, all three being on a straight line and J7 midway between I7 and K7.
- (H9) Quarter corner common to Sections 22 and 27. 1849 Established by Wm. Burt, Deputy, midway and on the Section line between Section corners 40.41 chains east and west. Set Y. Birch post. Sugar 6" S50°W 13 links, Maple 5" N72°E 25 links. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K7) The original post and accessories were not recovered. Found a 1" ID iron pipe with mushroomed top on a straight line through the 1976 monuments at I7 and J7 and at a distance from J7 that is substantially that observed between I7 and J7. Accepted same as the 1976 position and as the best available evidence of the position of the original corner. Cut the mushroomed top from the pipe and installed a 2" alum. cap on same.
- (H9) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section Corners 2627.23' east and west. The position falls in the center of a 2-track woods road.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K7) Found 1"ID Iron pipe, set 2" alum. MI Set measuring nail with MDNR tag in the s: 8" Sugar N12°E 12.6' mrkd "S13 NI 5" Sugar S43°E 17.6' "S24 NI 5" Maple S05°W 7.4' "S23 NI 4" Sugar S81°W 16.35' "S23 NI Set sq'd cedar post adjacent. E= 7884510.002 N= 216617 818	ide of: BT" BT" BT" BT"	14" Hemlock S33°E 20.85' 6" Sugar S32°W 22.3' 7" Sugar N48°W 23.85' Set sq'd cedar post adjacent.	ag in the side of: mrkd "1/4S NBT" do do do
E= 7884510.002 N= 216617.818		E= 7882065.520 N= 215089.591	L

Bearings are magnetic.	Coordinates are	MCS83 in meters,	NAD83 (2011) Epoch	2010.00 datum,
Coord. Ref.=	=NGS PID D08499:	N= 221257.621 m	E= 7884435.168 m.	0.5

For the Michigan Department of Natural Resources, Forest Resources Division

Date

Surveyor's Michigan License No. 33986

> JRVEYOR FORM APPROVED BY MICHIGAN STATE BOARD

STEPHAN YSZKOS

LAND

01/21/2016