

SURVEY & REMONUMENTATION

MAY 05 1997

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **COMMISSION**

Baraga
(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|---------------------------|-------|
| 1. Public Land Survey | T <u>50N</u> R <u>30W</u> | A-1* |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous | S _____ T _____ R _____ | _____ |
| Property in Sec. | S _____ T _____ R _____ | _____ |

RECEIVED FOR RECORD THIS 20TH DAY OF DECEMBER, 1996 AT 10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGES 711-712.

Richard M. McIntyre
BARAGA COUNTY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Michael Mileski, in a field survey on November, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-1; Northwest Corner Section 6, T50N, R30W;

See back of form.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-1; Northwest Corner Section 6, T50N, R30W;

Found no evidence bearing upon the position of the original corner. Reestablished this corner on line between the standard corners immediately to the east and west at the proportionate distance. From this position, Mr. Thompson's corner as perpetuated by Mr. Schmeling bears N08°E a distance of 7.73 feet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-1; Northwest Corner Section 6, T50N, R30W;

Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 10" above ground.

Set 7" spike	S/side	7" Sugar Maple	S66°E	7.54'
Set 7" spike	SE/side	13" Sugar Maple	S40°W	40.33'
Set 7" spike	N/side	13" Sugar Maple	N76°W	43.70'
Set 7" spike	E/side	11" Sugar Maple	N37°W	38.37'
		1" Iron Pipe w/4" cap	N08°E	7.73'
		Location Post	North	1.0'

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.

*This corner is also M-1 of T50N, R31W.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

APPROVED LAND CORNER
P.A. 345 OF 1990
Baraga County

Michael Mileski
12-18-96



Signed by Michael Mileski

Date 18 Dec 1996

Surveyor's Michigan License No. 39091

A. Description of original monument and accessories and/or subsequent restoration:

A-1; Northwest Corner Section 6, T50N, R30W;

Originally established during U.S. Survey conducted by John Burt, D.S. in 1846 and monumented with a wood post witnessed by a

Sugar	14	S24°E	59 lks.
Sugar	10	S47°W	20 lks.

According to the field notes of his survey of the east line of section 1, T50N, R31W, Norman Thompson, RLS #4348 reestablished this corner by measurement from the S¼ corner of section 33, T51N, R30W on 11 September 1946. Mr. Thompson monumented the corner with a hemlock post.

Mr. Thompson's corner location was further perpetuated by Robert Schmeling, RLS #8317 and monumented with a 1" diameter iron pipe with 4" brass cap found projecting 18" above ground.

SURVEY &
REMONUMENTATION

MAY 05 1997

COMMISSION