

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 51N R 30W	B3
	T R	
	T R	
2. Property Controlling in Section	S 8 T 51N R 30W	D4
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3		7				9		10		11		12	
4													
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 08/21/13 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B3) Quarter corner common to Sections 6 and 7. 1846 - Established by Hubbard and Ives, Deputy  
Surveyors, on the Section line between Section corners 40.00 chains east and 40.98 chains west. Set  
post. Cedar 16" N14°W 09 links, Fir 8" S50°E 13 links. Circa. 1942 - Norman T. Thompson RLS states he  
found the Cedar OBT "OK, set post" and made two new bearing trees: Sugar 8" N65°E 48 ft., Sugar 8"  
S23°W 42 ft. Found no subsequent record.

(D4) Center of Section 8. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B3) The original post and accessories were not recovered. Found no monumentation at the corner  
position. Found a 15" dia. Sugar, initially suspected to be Thompson's NE NBT, with many blazes,  
including two facing SW, an unreadable metal location poster affixed (grown into tree radially), and  
with double strand of fence wire passing through the tree. Cut the tree down to search for possible  
Thompson iron marks but found none, possibly due to interior rot. The second Thompson NBT was not  
recovered. This area has been disturbed by road construction and by a 2' deep by 20' wide creek. The  
Maple, which I did not accept as the 1942 NBT is 1 ft. south and 30' east of the position subsequently  
monumented. Having no other evidence of the position of the original corner on the ground, I  
reestablished it on the Section line between Section corners 2624.86' east and 2689.17' west, being  
proportionate to the original record.

(D4) Established the position for the corner at the intersection of straight lines connecting opposite  
1/4 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B3) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
8" Elm N16°E 29.15' mrkd "1/4S NBT"  
12" W.Spruce N79°E 54.9' do  
8" Elm S69°E 28.3' do  
8" Elm S46°E 29.9' do  
Set sq'd cedar post adjacent.  
E= 7911463.718 N= 228962.450

(D4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
4" Maple N65°E 7.9' mrkd "C1/4 BT"  
10" Sugar S34°E 12.9' do  
15" Hemlock S55°W 17.8' do  
10" Maple N43°W 8.95' do  
Set sq'd cedar post adjacent.  
E= 7913052.790 N= 228128.235

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/08/2013

For the Michigan Department of Natural Resources, Forest Resources Division

