SURVEY & REMONUMENTATION

Signed by

Surveyor's Michigan License No.

39091

LAND CORNER RECORDATION CERTIFICATE MAY 0.5 1997 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in (County Barego MAN S Located In: Corner Code # RECEIVED FOR RECORD THIS 30TH DAY OF JULY 1996 AT 10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER Public Land Survey T 51N R 33W RECORDATION RECORDS ON PAGES _ R 641 - 642. T _ R _ Τ_ 2. Property Controlling _ R Τ_ in Section 3. Miscellaneous Property in Section Register of Deeds Stamp & File Number __, Recorded Plat Private Claims ___ _, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: D-3; One-quarter Corner common to Sections 5 and 8, T51N, R33W; APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County See back of form. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: D-3; One-quarter Corner common to Sections 5 and 8, T51N, R33W; Recovered the BLM monument and all accessories as described in Part A. I did not find Mr. Hall's cedar post. From this monument the centerline tangents of Bear Town Road extend to the east and to the south. I left the BLM monument in place and stamped the cap "PA 345 1996". Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: D-3; One-quarter Corner common to Sections 5 and 8, T51N, R33W; MICHAEL D MILESKI See back of form. PROFESSIONAL SURVEYOR No. 3909 OFESSION

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983 A. Description of original monument and accessories and/or subsequent restoration:

D-3; One-quarter Corner common to Sections 5 and 8, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a hemlock post witnessed by a

Yellow Birch 12 N41°W 19 lks. and a Yellow Birch 10 N52°E 06 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, a 6 inch diameter cedar post projecting 5½ feet above ground with the southeast face scribed as to location as set in 1935 by Marshall J. Hall, Junior Engineer, U.S. Indian Service was found and accepted. The BLM recovered Mr. Hall's field notes of the "Carp River Truck Trail" survey at the Federal Records Center, Chicago, Illinois. The BLM remonumented the corner with a 2½" x 30" aluminum pipe and cap stamped as to location and noted the following new bearing trees:

Maple 7 S84°E 131/2 lks. (8.91')

Found sugar maple presently alive and 9" in dia. having a partially healed lower blaze with some scribing visible.

Set 7" spike N/side Measured S88°E 8.91'

Maple 6 N34°W 30 lks. (19.80')

Found red maple presently alive and 9" in dia. having an open lower blaze with scribing visible.

Set 7" spike W/side Measured N40°W 19.80'

- C. Description of monument for corner and accessories established to perpetuate locating the position:
 - D-3; One-quarter Corner common to Sections 5 and 8, T51N, R33W;

Found 2½" dia. aluminum pipe with 3" aluminum cap appropriately stamped as to location as set by the BLM in 1984.

Set 7" spike NW/side 11" Red Maple N53°E 31.38' Set 7" spike NW/side 9" Sugar Maple S43°W 38.34' Location Post S20°E 1.0'

All of the above new bearing trees are marked with upper and lower blazes, scribed "NBT", and painted red.

The following new bearing trees were established by the BLM in 1984. The condition of each is described in Part A.

Set 7" spike N/side 9" Sugar Maple S88°E 8.91' Set 7" spike W/side 9" Red Maple N40°W 19.80'

The above BLM new bearing trees were painted red.

SURVEY & REMONUMENTATION

MAY 0 5 1997

COMMISSION