LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970 as Amended

E			
FAI	ר רח	rne	rs in

Baraga	Located In:	Corner Code #		
(County)	- A 9			
1. Public Land Survey	TR			
2. Property Controlling in Section	S 4 T 52N R 31 S T R	SMC north of F3		
3. Miscellaneous Property in Sec.	S T R R			
4. Lot No. Rec 5. Private Claims	corded Plat		Register of Deeds St	GRZJKLM
above were in conformance with instructions of the United States I a Court of Law and /or that the co	74, Michigan P.A. of 1970, the or regulations and rules therefore as Department of the Interior, Burea corner points mentioned in lines 3, d of Land Surveyors or by a	do hereby state corner points mentioned in lines 1 and 2 required in the current manual of survey au of Land Management or by a decree of , 4 and 5 above were in conformance with Decree of a Court of Law; established,	, 5 , 6 — 18 — 17 — 16 , 7 , 8 — 19 — 20 — 21	10 11 12 15 14 13 22 23 24
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and	range, may be recorded	9 10 30 29 28 11 12 31 32 33	27—26—25— 34—35—36—
A. Description of original m	Onliment and accessories an	d/or subsequent restaurations	13	

(SMC north of F3) Special Meander Corner on the N-S 1/4 line of Section 4, at Keweenaw Bay. Previously established by R.W.Crampton PS, date unkown, who set a 3/4" ID iron pipe being the NW corner of a subdivision of Government Lots 1 and 2, Section 4, 1185.91' north of Quarter corner F3.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(SMC north of F3) Found a 3/4" ID iron pipe in good condition with the following witness trees bearing a nail and tag stamped "Survey Point LLS 24591 Do Not Disturb": 7" W.Birch S86E 15.9', 6" Spruce S53E 35.7', 10" Spruce S20W 17.1'. I found the distance south to Quarter corner F3 to be 1185.78'. I note that the bearing of the line south from this monument to F3 is parallel to the east line of Section 4 (G2 to G3) and I accept the monument as a careful and faithful determination of the N-S 1/4 line of Section 4, being on the line between Government Lots 2 and 3. The monument may not mark the true position of the SMC, i.e., not at the statutory OHWM of Lake Superior.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(SMC) Found 3/4" iron pipe projecting 12" a.g. Set measuring nail with MDNR tag in the side of: 6" Spruce NO5W 6.8' mrkd "MC BT"

6" Spruce S86E 3.35' 6" Spruce S16E 11.65'

do do

7" W.Birch S62W 14.7'

Set sq'd Cedar post adjacent.

Bearings are magnetic.

STEPHAN J SZYSZKOSKI LAND RYEYOR AND SV

Signed by	
-----------	--

Surveyor's Michigan License No.

33986

Date

08/10/2011

For the Michigan Department of Natural Resources, Forest Management Division