

SURVEY & REMONUMENTATION

FEB 23 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Baraga</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>52N</u> R <u>33W</u>	<u>#9) South MC</u>
	T _____ R _____	<u>between A-2 and</u>
	T _____ R _____	<u>A-3</u>
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	

RECEIVED FOR RECORD THIS 31ST
DAY OF DECEMBER A.D. 1997 AT
10:30 A.M. AND RECORDED IN
LIBER 4 OF LAND CORNER
RECORDATION RECORDS ON PAGE
824

Relda Bishop
BARAGA COUNTY REGISTER OF DEEDS
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Michael Mileski, in a field survey on 18 November, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC #9; South Meander Corner between A-2 and A-3, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Maple 24 S17°E 34 lks.

No subsequent record evidence bearing upon the location of this corner was found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC #9; South Meander Corner between A-2 and A-3, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the SW corner of section 6 and the W ¼ corner of section 6. This corner position falls approximately 42 feet south of the right (south) bank of the Sturgeon River. This corner also falls 5 feet east of a north-south fence line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC #9; South Meander Corner between A-2 and A-3, T52N, R33W;

Set a 1" (I.D.) x 36" galvanized iron pipe with cap stamped as to location flush with the ground.

Set 7" spike	NE/side	9" Black Ash	S46°E	33.28'
Set 7" spike	W/side	Power Pole	S01°W	72.13'
Set 7" spike	N/side	10" Sugar Maple	N89°W	14.12'
Set 7" spike	S/side	6" Sugar Maple	N69°W	43.79'
	6' Steel fence post w/ yellow sign	East		1.5'

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

APPROVED LAND CORNER
P.A. 345 OF 1990
Baraga County

10-9-97
[Signature]



LIBER 4 PAGE 824

Signed by [Signature]
Surveyor's Michigan License No. 39091

Date 23 Dec 1997