

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Baraga

(County)

Located In:

Corner Code #

1. Public Land Survey	T <u>53N</u> R <u>31W</u>	<u>L13</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u>36</u> T <u>53N</u> R <u>31W</u>	<u>15</u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

Nov 28 2001

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.


A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:
 (L13) Quarter corner common to Section 36 T53N-R31W and Section 1 T52N-R31W. Reestablished by proportionate measurement in 1973 by A.O. Enger RLS. 1"IDx36" iron pipe with 4" aluminum cap. Red Maple 6 S40E 6.0', W. Birch 6 N72 1/2E 17.4'. Corner recorded in L1 of LCRCs, P137, Baraga Co. Records.
 (15-Sec. 36) West 1/16 corner between Section 36 T53N-R31W and Section 1 T52N-R31W. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 (L13) Recovered the 1973 monument as described, in good condition and at record bearing and distance from the 1973 accessories. The R. Maple is a cut stump, the W. Birch is in good condition with overgrown blazes. I verified the position of the monument with respect to the adjacent section corners and accept it as a careful and faithful reestablishment of the position of the corner.
 (15-Sec. 36) Established the corner midway and on a line of mean true bearing between Section corner 1319.48' west and Quarter corner 1319.48' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L13) Found 1" ID I. pipe w/ 4" alum. MI Dept. of Cons. cap. Blazed and scribed: 6" Spruce S89W 32.5' "1/4S NBT" 8" Maple S18W 26.8' do 8" Maple N24E 40.7' do The 1973 wit: 7" W. Birch N78E 17.4' overgrown blazes Squared cedar post adjacent. Bearings are magnetic. Distances are to notch in lower blaze.	(15) Set 1" IDx32" I. pipe with 4" alum. MDNR cap. Blazed and scribed: 12" Hemlock S61E 18.0' "1/16S BT" 8" Hemlock S17E 25.1' do 8" Cedar S34W 12.2' do 6" Cedar N30W 7.7' do Set squared cedar post adjacent. Bearings are magnetic. Distances are to notch in lower blaze.
--	---



Signed by Stephan J. Szyszkoski Date 3/19/02
 Surveyor's Michigan License No. 33986