LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Benzie	L	Located In		Corner Code #		
(County)						
1. Public Land Survey	T T	25N R	14W	<u>L9</u>		
Property Controlling in Section	ST	R			_	
3. Miscellaneous	S T _	R				
Property in Section	s T	R				
	s T _	R	-			Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	:	_			ARCDEEGHILVI
5. Private Claims:		<u>.</u>				A B C D E F G H I J K L M
I, <u>Craig W. McVean</u> , in a field survey on <u>Oct. 5</u> , 20 <u>10</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:					3 4	
NOTE: Not more than 2 corners, all in the same town and range, may						
be recorded on this certificate.						
						12 -31 -32 -33 -34 -35 -36 -
						13
A. Description of original monument and accessories and/or subsequent restoration:						
1) Sugar 20 N20°E 42 L. 2) Hemlock 24" S13°W 14 L.					- 85';	- 1994 – Unrecorded Survey – R. Max Harris Land Surveying #94-3267 – Pipe fd. raised with ½" I.R. – Same witnesses as 1988 LCRC 2002 – Unrecorded Survey – Mitchell and Assoc. #20020701 – R. F. Mitchell – Fd. 1" pipe on centerline Rd. to East. 6) N56°E 15" Cherry 67.61'; 7) S42°E P. Pole 62.18'; 8) S22°W 18" R. Pine 93.42'; 9) S75°W 6" Elm 78.47'. South centerline to W. 5'; West centerline to S. 5'.
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:						
L9 – ¼ Corner common to Section 24 & 25, T25N, R14W – Fd. ½" x 18" long rebar near surface at North edge of Gravel road 'T' intersection. Dug down and find ¾" x 2.75' long iron pipe with union on top under ½" rebar – Down 1.6'. Condition of Witnesses as follows: Witnesses #1, 2 & 3 are gone. Witnesses #4 & 5 – Fd. stps. Witnesses #6, 7, & 8 are OK. #9 not checked. ¾" iron pipe accepted as the best available evidence of the position of the original corner.						
C. Description of monume	ent for corner an	d access	ories est	ablished to p	erpetu	uate locating the position of the corner:
<u>L9</u> – Replaced ½" rebar a	and ¾" iron pipe 0.8' below grade	with Star	nped 3" E	Benzie Co. R		Brass Cap on ¾" x 36" iron pipe encased in 4" x 36" long
N48°W 37.09' to set N56°E 67.53' to Fd. S43°E 46.04' to Fd. S25°W 93.36' to Fd. North 32.95' to Fd. 5 S41°E 62.09' to Set	N & T at fd. nail 60d nail in SE si ½" CIR #25845 60d nail in E. si ½" CIR #28417 –	in SW s ide Tw. 1 – RMH de 20" R - RFM	0" & 12" . Pine (#8	Cherry (#6) 3)		CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088
	· n.	,	1. 6	1 /		39088 No.
Signed by:	my W	1	Me 1	on	Date	9: 12/16/2011 PAROPESSIONAL
Surveyor's Michigan L	icense No.:	3908	38			/