REMONDATION

MAR D 2 1889

For corners in CITON

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Benzie (Cou		Located In:	Corner Coc	le #			OF MICHIGAN IZIE COUNTY
1. Public La	ind Survey		R_13W R	B-3			ECORDED
 Property in Section Miscellar Property 	n neous	ST_ ST	RRR			MICHE REGIS H PAG	1999 9:12:07 AM TILLE R. GRAY STER OF DEEDS SES ONE
						Register	of Deeds Stamp & File Nur
4. Lot No.	, Red	corded Plat					
			· · ·		Α	всов	F G H I J K L M
5. Private C	laims		•		1 2 - 2 - 3 -	6 - 5 -	4 3 2 1
state that under mentioned in his therefore as rec States Departm Court of Law a in conformance Decree of a Co found as expre	er requirements of a nes 1 and 2 above quired in the current nent of the Interior nd /or that the core with the rules of urt of Law; establi ssed below:	P.A. 74, Michigan P.A. were in conformance of manual of survey in the Bureau of Land Martner points mentioned the Michigan Board of ished, re-established,	July 14, 19 98 do A. of 1970, the corner e with regulations and instructions of the Unit nagement or by a decre in lines 3, 4 and 5 ab of Land Surveyors or by monumented, recover	points rules ed ee of a ove were y a	4 - 5 - 6 - 7 - 8 - 9 - 10 - 11 - 12 - 13 - 13 - 13 - 13 - 13 - 13	18 17 19 20 19 19 19 19 19 19 19 19 19 19 19 19 19	-16
certificate.	more than 2 co	rners, an in the sai	me town and range	, may be record	ied on this		
A. Descripti	ion of original m	nonument and acce	essories and/or subs	sequent restora	tion:		
<u>B-3</u> – GLO –	Beech 10" N12°E 24L -				DNR Project # 31-93100 - Carl Roser - 1981 Rec. Survey - L. 1,P. 868 - R.M. Harris - 1986		
- Co. Si	Hem. 10" S20° ir. 8k., P. 109 -	°W 5L - D.F. Holden – 18	875		FND. Mon.		
Set - DNR P FND	post from origin Project # 71-6), %" Pipe & Cro led DNR Mon, S	nal BT's Carl Roser – 197' ockery buried in S' Set Cedar post w/		vel Rd. '.	In ac	ied by Pee cordance nan	er Group with P.A. 345)
•	8" W. Pine N64 4" W. Pine S46				Date	July 8,1	998
,	7" W. Pine \$48	3°W 40.75′					
B. Descript	ion of corner ev	idence found and/	or method applied i	n restoring or re	eestablishing co	rner:	
E-W gr	avel Rd. FND.	4" DNR Alum. Cap	,R13W. FND. ¾″x o on 1″x 36″ long li on of the original co	on Pipe alongsi	Pipe w/ Crocker ide 0.08' N. & 0	y around; dov 0.04' E. Acce	vn 28", 2'± N. of CL. pt ¾" Iron Pipe as
C. Description	n of monument	for corner and ace	cessories establishe	d to perpetuate	e locating the po	sition of the	corner:
B-3 - Replace Placed North: South *S34°W S40°E *N38°E	e ¾" Iron Pipe 8 broken crocker 33.08' to PS Ca 33.6' to face 5' 50.37' to set I 52.23' to set N	& DNR Mon. w/ Be y around base of N ap # 25845 on ½" " Cedar post w/ Lo N&T in NW. Side 9 I&T in NE. Side 14 I&T in SE. Side 15	enzie Co. Concrete l Monument as a men ' Rebar. Set blue C	Monument, downorial arsonite post will 'XBT'	wn 0.8′.	side	CRAIG W. McVEAN PROFESSIONAL SURVEYOR NO
Simple /	On M	V. M. V.	<i>)</i>			- 0/-	o loca
Signed by(Surveyor's M	ichigan License		39088			Date <u>9/3</u>	11798

|LIBER 2 PAGE 250