

SURVEY & REMONUMENTATION

APR 26 1995

BERRIEN COUNTY REMONUMENTATION PROGRAM
LAND COMMISSION RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

Dec 2 11 11 AM '94

Berrien County
REGISTER OF DEEDS
BERRIEN COUNTY MICHIGAN

RAITIFIED BY THE BERRIEN COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 344 OF 1990

R. J. Harner

11-29-94
For corners in
Berrien
(County)

Located in: _____ Corner Code # _____

- | | | | |
|---------------------------------------|-------------------------------|-------|-------|
| 1. Public Land Survey | T <u>6</u> S., R <u>17</u> W. | G-3 | |
| | T _____ R _____ | _____ | _____ |
| | T _____ R _____ | _____ | _____ |
| | T _____ R _____ | _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ | _____ |
| | S _____ T _____ R _____ | _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ | _____ |
| | S _____ T _____ R _____ | _____ | _____ |
| 4. Lot No. _____, Recorded Plat _____ | | | |
| 5. Private Claims _____ | | | |

12/02/94 111W8049 A99
CORNER \$7.00
12/02/94 111W8049 A99
Register of Deeds Stamp & File Number
STATE REMON FEE \$2.00

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3							•						
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, R. J. Harner, in a field survey on November 30, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- | | |
|-----------------------------------|--|
| <u>G-3</u>
Government - post | Berrien County Road Commission - rail road spike |
| B. Ash 10" S. 15 2/3° E. 30 links | 16" Maple S. 45° W. 35.10' |
| B. Ash 13" N. 45 1/3° E. 32 links | S.E. Corner Conc. Hdwl. N. 45° W. 28.00' |
| | S.W. corner Conc. Hdwl. N. 45° E. 28.30' |
| | E.R. Stefan June 12, 1980 - rail road spike |
| | nail in 24" Maple S. 45° W. 35.42' |
| | nail in power pole South 93.92' |
| | iron South 33.00' |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-3
found rail road spike over stone

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-3
set iron and brass cap in monument box
P.K. nail in 24" Maple S. 37° W. 35.53'
iron South 33.00'
nail and washer in power pole N. 12° W. 103.21'
nail and washer in 6" Maple S. 65° E. 80.61'

*Accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by *R. J. Harner* Date 30 Nov. 1994
Surveyor's Michigan License No. 22436

